



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 May 2022, 18:04:18
Transaction Number	41745381 (CC10008)	Queue Number	312309



Chassis Number	2FABP7EV2BX131362
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Crown Victoria
Model Year	2011
Color	Silver
Mileage	146434 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REPAIRED,REPAINTED & REFITTED & REAR BOTH SIDE PORTION REPAIRED,REPAINTED	مدكار
01.B Doors	PORTION REPAIRED,REPAINTED	أبواب
01.C Roof	PORTION REPAIRED,REPAINTED	السقف
01.D Bumper	MISALIGN	دعامية
01.E Sign of front accident		وجود مؤشر لحادث في المقدمة
01.F Other	FRONT FENDER FRAME, RADITOR SUPPORT REPAIRED	اخرى
01.G Paint	REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.H Bonnet	REPAIRED,REPAINTED,REFITTED & SHOCK WEAK	غطاء المحرك
01.I Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.J Pillars	FRONT LEFT SIDE A/ PILLAR DOOR MODIFIED HOLE FOR FOG LIGHT	القوائم
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
03 Transmission Condition		الجير

DEFECT	REMARKS	
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
04 Engine Condition		المحرك
04.A Visual Engine Condition	OK	حالة المحرك النظري
04.B Mount	MOUNT RUBBER CUT	كرسي
05 Engine Cooling System		نظام تبريد المحرك
05.A Radiator Condition	RADIATOR LOWER SUPPORT BEND	حالة المبرد
06 Chassis Condition		الشاصي
06.A Chassis	FRONT LEFT SIDE CHASSIS END LOWER EDGE MINOR BEND	الشاسيه
07 Interior Condition		الحاله الداخليه
07.A Door Panel	PORTION LOOSE	لوحة بطانة الباب
07.B AC Condition	NOT WORKING	المكيف
08 Seats Condition		المقاعد
08.A Seat Condition	FRONT BOTH SIDE SEATS HAVE MINOR CUT & HAND REST LEATHER WORN OUT	حالة المقاعد
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية
10 Steering Condition		المقود
10.A Steering Oil	MINOR OIL LEAK	زيت المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	2FABP7EV2BX131362
Vehicle Make :	FORD
Vehicle Model :	CROWN VICTORIA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	235665 Kms.
Origin : United States	Model Year : 2011
Gear Type : Automatic	Engine Size : 4600 CC
Engine No : nil	Horse Power : 239
Axles No : 2	Cylinders : 8
No Of Doors : 4	No Of Seats : 5
G. V. W. : 2000 Kgs.	Empty Weight : 1872 Kgs.

Certificate Number :	5-TAS-2022-16779756
Inspection Date :	18-05-2022
Certificate Print Date :	18-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	14 min 14 sec
Appointment Ref Number :	--
Start Time : 8:37	End Time : 8:51
Lane : 02	Token No. : 105
Attempt : 1	Prints No : 1

Carbon footprint



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

16833 KM	1733 L	2808 AED	4.2 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 9 %	Service brake imbalance on rear axle 16 %	Parking brake imbalance between LHS and RHS 16 %	Vehicle on Petrol CO Reading 0.01 %
Vehicle on Petrol HC Reading 3 PPM VOL			

Inspection Remarks: Front bumper, bumper frame, bulk head, radiator support repaired, minor steering oil leak, chassis getting rusty

Payment Details

Inspection Performed by 34944	Payment Method Cash	Transaction Number 16779756	Service Fees AED 170 Collected on 18/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Hussain Basha Akeel

i This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

i Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.