



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>18 Jan 2023, 12:56:08</b>
Transaction Number	<b>52373270 (CC10006)</b>	Queue Number	<b>657739</b>



Chassis Number	<b>JM7BJ12M141228154</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mazda</b>
Model	<b>323</b>
Model Year	<b>2004</b>
Color	<b>--</b>
Mileage	<b>01 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Rusty	AVOID UNDER BODY ,SUSPENSION PARTS GETTING RUSTY.	صدأ
01.B Other	BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED.	اخرى
01.C Bumper	MISALIGN PORTION DAMAGED.	دعامية
01.D Vehicle Color	BIEGE	لون المركبة
01.E Floor	DENT.	الارضية
01.F Sign of back accident		وجود مؤشر لحادث في الخلف
01.G Paint	BODY REPAIRED ,REPAINTED ,DENTS SCRATCHES,PAINT FADED ,RUSTY .	الصبغ
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A Odometer reading	NOT CHECKED,	قراءة عداد المسافات
02.B Mirror	LEFT SIDE DAMAGE.	المرآيا
02.C Door Panel	LOOSE.	لوحة بطانة الباب
02.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.E AC Condition	NOT CHECKED.	المكيف
<b>03 Steering Condition</b>		<b>المقود</b>

DEFECT	REMARKS	
03.A Steering Oil	OIL LEAK.	زيت المقود
03.B Tie Rod End	WORN OUT,	مؤخرة الرودادات
03.C Axle	BOOT CUT.	اكسلات
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Shock Absorber	LEAK.	ممتص الصدمات
04.B Suspension Subframe	RUSTY	
04.C Ball Joint	BOOT CUT.	مفصل كروي
04.D Arms	LOWER ARM BUSHES CUT .	ازرع
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK.REFITTED	حالة المحرك النظري
05.B Mount	CUT.	كرسي
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	REAR RIGHT SIDE CHASSIS EXTENSION REPAIRED.	الشاسيه
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Visual Gear Box Condition	REFITTED OIL LEAK.	حالة الجير النظري
07.B Road Test	NOT CHECKED.	فحص علي الطريق
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2018 EXPIRED ,CRACKED .	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2018 EXPIRED ,CRACKED .	الاطار الخلفي
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.