

Queue Number

2822620

Transaction Date

01 Oct 2026, 14:24:10

Site Name

840 - Emirates Auctions

Transaction Number

62096017 (CC10013) (CC10011)



Vehicle Details

Chassis Number	1GKFK36389*****
Specification	GCC Specification
Make	GMC
Model	Yukon
Model Year	2009
Color	Black
Mileage	130181 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED ,EXCEPT ROOF , DENTS SCRATCHES PORTION FADED GETTING RUSTY	الصبغ
01.C Doors	REFITTED , FRONT LEFT SIDE DOOR SQUEAKING SOUND WHEN OPENING	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR MUDDY DIRTY	الارضية
01.F Bumper	MISALIGN , FRONT & REAR EXTRA BULL BAR , BOTH SIDE STEPPING BOARD MODIFIED	دعامية
01.G Roof	BOTH SIDE ROOF BAR MODIFIED GETTING RUSTY	السقف
01.H Bonnet	REFITTED	غطاء المحرك
01.I Other	EXTRA BAR FITTING WITH BODY	اخرى
01.J Trunk	MISALIGN , RIFFITED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME MUDDY DIRTY RUST PROOFED GETTING RUSTY / EXTRA BAR FIXING WITH CHASSIS	الشاسيه
02.B Chassis Number	VIN RUST PROOFED NOT VISIBLE TO CHECK	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Belt	REAR BOTH SIDE NOT WORKING	حزام الأمان
04.B Seat Condition	PORTION DAMAGE , BACK COVER REAR BOTH SIDE PANEL DAMAGE , LEFT SIDE ADJUSTABLE LEVER DAMAGE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	WATER TANK COVER MISSING	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10.B Axle	BOOT CUT	اكسلات
11 Interior Condition		الحالة الداخليه
11.A Other	CENTER CONSOLE PANEL WORN OUT PORTION LOOSE DAMAGE , INETERIOR PARTS GETTING RUSTY , REFITTED	اخرى
11.B Mirror	BOTH SIDE VIEW MIRROR AUTO MATIC FOLDING NOT WORKING , BOTH SIDE HOUSING LOOSE	المرايا
11.C AC Condition	OK , CONTROL PANEL BUTTON FADED , REAR CONTROL SWICTH DAMAGE	المكيف
11.D Floor Matting	DIRTY	فرش الأرضيه
11.E Audio	CONTROL BUTTON PORTION FADED	صوتيات
11.F Dash Board	DAMAGE	لوحة القيادة
11.G Roof Ceiling	PORTION DAMAGE	بطانه السقف
11.H Sun Visor	LEFT SIDE WORN OUT , RIGHT SIDE DAMAGE	حاجب الشمس
11.I Door Panel	PORTION WORN OUT , BOTH SIDE LOWER DOOR BEADING RUBBER WORN OUT , BOTH LEFT SIDE INNER SKIRT COVER DAMAGE	لوحة بطانة الباب
11.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم



Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae