

Queue Number

2676123

Transaction Date

26 Aug 2026, 13:30:47

Site Name

840 - Emirates Auctions

Transaction Number

17542088 (CC10006) (CC10006)



Vehicle Details

Chassis Number

VF12RRJR4H*****

Specification

GCC Specification

Make

Renault

Model

Captur

Model Year

2017

Color

Grey

Mileage

139299 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

FRONTBOTH SIDE BLASTIC PAINT CAN NOT CHECK, MOLDING, LOOSE PORTION DAMAGED

مدكار

01.B Paint

BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION FADED RUSTY

الصبغ

01.C Rusty

UNDER BODY PARTS, SUSPENTION GETTING RUSTY

صدأ

01.D Floor

UNDER FLOOR COVERD, PORTION RUST PROOFED, PORTION DENT, MUDDY

الارضية

01.E Bumper

MISALIGN,PORTION DAMAGED . FRONT LOGO PORTION DAMAGED

دعامية

01.F Bonnet

REPAIRED, REPAINTED, REFITTED

غطاء المحرك

01.G Other

FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED

اخرى

01.H Sign of front accident

وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis

COVERD,MUDDY, CHECKED VISIBLE AREA ONLY OK

الشاسيه

03 Engine Condition

المحرك

03.A Mount

BUSHES CRACKED

كرسي

03.B Engine Visual Condition

ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY

الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition

NOT CHECKED,REFITTED,OIL LEAK,PARTS RUSTY

الحالة النظرية للجير

Condition	Remarks	الحالة
04.B Gear Box Mount	BUSH CRACKED	كرسي الجير
04.C Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2022/2024 CRACKED, DAMAGED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023/2017 CRACKED, EXPIRED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK	ممتص الصدمات
07.B Arms	BUSHES CUT	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخرى
09.B Mirror	LEFT SIDE COVER PORTION DAMAGED	المرايا
09.C AC Condition	NOT CHECK	المكيف
09.D Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae