



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 18 Jan 2023, 15:59:51 |
| Transaction Number | 38378296 (CC10010) | Queue Number | 657743 |



| | |
|------------------|--------------------------|
| Chassis Number | JM7TB19A4A0203988 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Mazda |
| Model | CX-9 |
| Model Year | 2010 |
| Color | Red |
| Mileage | 202154 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|---|---|----------------------------|
| 01 Interior Condition | | الحاله الداخليه |
| 01.A AC Condition | OK | المكيف |
| 01.B Roof Light | FRONT DAMAGED | أنارة السقف |
| 01.C Other | INTERIOR DUSTY | اخرى |
| 01.D Sun Visor | LEFT SIDE MISSING | حاجب الشمس |
| 01.E Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 02 Lights | | الاضاءة |
| 02.A Head Light | LENS FADED | الاضاءة الرئيسية |
| 02.B Brake Light | CENTER BRAKE ASSEMBLY MISSING | نور الفرامل |
| 03 Body | | جسم المركبة |
| 03.A Paint | BODY PORTION REPAIRED , PORTION REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED | الصبغ |
| 03.B Bumper | PORTION DAMAGED,MISALIGN | دعامية |
| 03.C Doors | REAR RIGHT SIDE DOOR,ROCKER PANEL SKIRT MISSING | أبواب |
| 03.D Floor | UNDER FLOOR COVERED ,CHECKED ONLY VISIBLE AREA | الارضية |
| 03.E Bonnet | LOCK HANDLE DAMAGED | غطاء المحرك |

| DEFECT | REMARKS | |
|------------------------------------|--------------------------|--------------------------|
| 04 Engine Condition | | المحرك |
| 04.A Visual Engine Condition | OIL LEAK | حالة المحرك النظرى |
| 05 Transmission Condition | | الجير |
| 05.A Road Test | NOT CHECK | فحص علي الطريق |
| 05.B Visual Gear Box Condition | OIL LEAK | حالة الجير النظرى |
| 06 Steering Condition | | المقود |
| 06.A Axle | BOOT CUT | اكسلات |
| 06.B Steering Boot | BOOT CUT | ريلة المقود |
| 06.C Tie Rod End | BOOT CUT | مؤخرة الرودادات |
| 06.D Steering Oil | OIL LEAK | زيت المقود |
| 07 Suspension System | | ممتص الصدمات |
| 07.A Other | STABILIZER LINK BOOT CUT | اخرى |
| 07.B Ball Joint | BOOT CUT | مفصل كروي |
| 07.C Arms | LOWER ARM BUSH CUT | ازرع |
| 07.D Shock Absorber | LEAK | ممتص الصدمات |
| 08 Tires and Rims Condition | | الاطارات |
| 08.A Front Tyre | BOTH SIDE 2019 CRACKED, | الاطار الامامي |
| 08.B Rear Tyre | BOTH SIDE 2019 CRACKED, | الاطار الخلفي |
| 08.C Spare Tire &Tools | SPARE TIRE MISSING | الاطار الاحتياطي و العدة |
| 09 Seats Condition | | المقاعد |
| 09.A Seat Condition | EXTRA COVER | حالة المقاعد |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.