



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>24 Nov 2021, 18:40:25</b>
Transaction Number	<b>71531590 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1ZVHT80N485208768</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Ford</b>
Model	<b>Mustang</b>
Model Year	<b>2008</b>
Color	<b>Grey</b>
Mileage	<b>86944 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي
01.B Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
01.C Rear Tyre	BOTH SIDE 2014/2017 EXPIRED & CRACKED	الاطار الخلفي
<b>02 Seats Condition</b>		<b>المقاعد</b>
02.A Seat Belt	OK	حزام الأمان
02.B Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Fenders	REAR BOTH SIDE REPAIRED & REPAINTED	مدكار
03.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY & PORTION FADED	الصبغ
03.C Bumper	REPAINTED	دعامية
03.D Roof	LEFT SIDE ROOF RAIL REPAINTED	السقف
03.E Trunk	REPAINTED & PORTION FADED	صندوق
03.F Floor	REAR BOTH SIDE QUATER PANEL, WHEEL ARCH, RUNNING BOARD REPAIRED	الارضية
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>

DEFECT	REMARKS	
04.A AC Condition	NOT COOLING	المكيف
04.B Dash Board	PORTION DAMAGED	لوحة القيادة
04.C Mirror	LEFT SIDE INNER COVER DAMAGED & LOOSED	المرابا
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Gear Box	GEAR SHIFTING LEVER CONSOLE BOX DUST COVER MISSING	الجير
05.B Road Test	NOT CHECK	فحص علي الطريق
<b>06 Chassis Condition</b>		<b>الشاسيه</b>
06.A Chassis	REAR LEFT SIDE REPAIRED, FRONT LEFT SIDE INNER & REAR BOTH SIDE JOINT DENT	الشاسيه
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Engine Condition	MINOR OIL LEAK	حالة المحرك
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Arms	FRONT LOWER ARMS BUSHES CUT	ازرع
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	OK & LENS SLIGHTLY FADED	الاضاءة الرئيسية
09.B Indicator & Hazard light	REAR LEFT SIDE NOT WORKING	الاشارات
09.C Tail Light	REAR RIGHT SIDE PARK LIGHT NOT WORKING	الانارة
09.D Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
09.E Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
<b>10 Wipers and Arms</b>		<b>المساحات</b>
10.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
<b>11 Brake Condition</b>		<b>الفرامل</b>
11.A Disc&Drum	GETTING RUSTY	دسك ووطنابير الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Possession Certificate : 65932580

Chassis No : 1ZVHT80N485208768

Vehicle Make : FORD

Vehicle Model : MUSTANG

Vehicle Class : Light Vehicle

Body Type : Coupe

Fuel : Benzene

Color : Gray

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 139924 Kms.

Origin : United States Model Year : 2008

Gear Type : -- Engine Size : 6800 CC

Engine No : NONE Horse Power : 210

Axles No : 2 Cylinders : 6

No Of Doors : 2 No Of Seats : 4

G. V. W. : Empty Weight : 1400 Kgs.  
2000 Kgs.

Certificate Number : 5-TAS-2021-15559445

Inspection Date : 28-11-2021

Certificate Print Date : 28-11-2021

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Al Aweer

Total Time Taken :  
18 min 44 sec

Appointment Ref Number : --

Start Time : 17:26

End Time : 17:45

Lane : 01

Token No. : 208

Attempt : 1

Prints No : 1

## Parameter Readings

Service brake imbalance on  
front axle  
13 %

Service brake imbalance on  
rear axle  
3 %

Parking brake imbalance  
between LHS and RHS  
5 %

Vehicle on Petrol CO  
Reading  
2.99 %

Vehicle on Petrol HC  
Reading  
227 PPM VOL

## Inspection Findings

### Defects

Front and Rear Windshields  
REMOVE REAR TINTED FADED

Tire  
CHANGE FRONT LEFT SIDE TIRE SIDE WALL CRACK OPEN

### Issue

Obstructed

Cracked

### Severity

Major

Major

## Discrepancies

Engine Size Discrepancy in Engine Size

Old Value

6800

New Value

4000

Verified

## Inspection Remarks:

REAR LEFT CHASSIS REAR COMPARTMENT & LEFT SIDE WHEEL HOUSING REPAIRED CHASSIS passed bu ccm report no.20170201-001

## Payment Details

Inspection Performed by  
8008085  
62439

Payment Method  
Cash

Transaction Number  
15559445

Service Fees  
AED 170 Collected on 28/11/2021

Parking Slot No  
--

Service Name  
Registration Test

Attempt  
1

Received by  
Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

