



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Apr 2022, 10:30:41
Transaction Number	20761278 (CC10008)	Queue Number	312309



Chassis Number	1G1YY22G2X5105016
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Corvette
Model Year	1999
Color	Black
Mileage	140012 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	JERKING ,REFITTED,OIL SUMB REPAIRED WELDED,SIGN OF OIL WET	حالة الجير النظرى
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2017 CRACKED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2020/2014 EXPIRED CRACKED	الاطار الخلفي
03 Engine Condition		المحرك
03.A Visual Engine Condition	REFITTED,UPPER ENGINE COVER MISSING	حالة المحرك النظرى
04 Steering Condition		المقود
04.A Steering Oil	OIL LEAK	زيت المقود
05 Chassis Condition		الشاسي
05.A Chassis Number	CHASSIS NUMBER CHECK WINDSHIELD DOOR ONLY NOT VISIBLE ON CHASSIS FRAME	رقم القاعدة
05.B Chassis	BOTH SIDE MIDDLE CHASSIS MINOR DENT & REAR CROSS MEMBER BEND	الشاسيه

DEFECT	REMARKS	
06 Body		جسم المركبة
06.A Paint	BODY REPAINTED,VEHICLE COLOR YELLOW	الصبغ
06.B Bonnet	MISALIGN	غطاء المحرك
07 Interior Condition		الحالة الداخلية
07.A AC Condition	NOT WORKING	المكيف
07.B Power Window Switch	SWICH DAMAGED,NOT WORING ,LOOSE	مفتاح النافذه
07.C Roof Ceiling	ROOF INNER COVER MISSING	بطانه السقف
07.D Steering Wheel and control buttons	HORN NOT WORKING	عجلة القيادة وازرار التحكم
07.E Door Panel	DAMAGED,LOOSE	لوحة بطانة الباب
07.F Dash Board	SWITCH MODIFIED	لوحة القيادة
08 Lights		الاضاءة
08.A Fog light	NOT WORKING	كشاف الضباب
08.B Head Light	RIGHT SIDE LOW&HIGH BEAM NOT WORKING	الاضاءة الرئيسية
08.C Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية
10 Brake Condition		الفرامل
10.A Hand Brake	NOT WORKING	فرامل اليد
10.B Brake Pedal	BRAKE PEDAL HARD ,WEAK	دواسة الفرامل
11 Exhaust System		نظام العادم
11.A Modification	CATAYLIC CONVERTER MISSING &EXHAUST PIPE WELDED	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	1G1YY22G2X5105016
Vehicle Make :	CHEVROLET
Vehicle Model :	CORVETTE
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Black, Yellow
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	--
Origin :	United States
Model Year :	1999
Gear Type :	Automatic
Engine Size :	6200 CC
Engine No :	NO
Horse Power :	345
Axles No :	2
Cylinders :	8
No Of Doors :	2
No Of Seats :	2
G. V. W. :	1850 Kgs.
Empty Weight :	1450 Kgs.

Certificate Number :	5-TAS-2022-16942465
Inspection Date :	07-06-2022
Certificate Print Date :	07-06-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	9 min 15 sec
Appointment Ref Number :	--
Start Time :	13:30
End Time :	13:39
Lane :	03
Token No. :	164
Attempt :	2
Prints No. :	1

Inspection Findings

Defects	Issue	Severity
Dip beams(Low Beams) headlight	Defective	Major
Odometer Reading	No Reading	Major
Bulkhead/Cross member REPAIR RADIATOR LOWER SUPPORT FRAME	Badly repaired	Major
Engine CHANGE OIL PAN WELDED REPAIRED STILL LEAK	Others (Major)	Major
Tire CHANGE FRONT RIGHT SIDE OLD & INNER CRACK	Date of manufactured tampered or expired	Major
Battery	Unsecure	Major

Inspection Remarks:

FRONT BOTH SIDE CHASSIS END,CHASSIS NUMBER AREA,B/S FENDER FRAME,SUB FRAME,RADIATOR FRAME REPAIRED. Both side middle chassis lower part dent

Payment Details

Inspection Performed by 59460	Payment Method Cash	Transaction Number 16942465	Service Fees AED 70 Collected on 07/06/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
 - Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
- تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

