



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **22 Sep 2022, 12:00:42**
 Transaction Number **68203668 (CC10009)** Queue Number **594412**



Chassis Number **WBAHN81006DT18586**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **BMW**
 Model **Alpina B7**
 Model Year **2006**
 Color **Beige**
 Mileage **104180 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018 & BADLY CRACKED	الاطار الخلفي
02 Suspension System		ممتص الصدمات
02.A Arms	LOWER ARM BUSHES CUT	ازرع
02.B Ball Joint	BOOT CUT	مفصل كروي
03 Lights		الاضاءة
03.A Tail Light	REAR TAIL LIGHT COVER PORTION CRACKED	الانارة
03.B Indicator & Hazard light	REAR RIGHT SIDE INDICATOR NOT WORKING	الاشارات
03.C Other	LIGHTS MAIN SWITCH NOT WORKING	اخرى
03.D Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04 Body		جسم المركبة
04.A Bonnet	SHOCK WEAK	غطاء المحرك
04.B Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA	الارضية
04.C Windshield	REAR CURTAIN DAMAGED	زجاج
04.D Paint	BODY MINOR DENT ,SCRATCHES	الصبغ

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	MINOR OIL LEAK & REFITTED,JERKING	حالة الجير النظرى
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
07 Chassis Condition		الشاصي
07.A Chassis	CHASSIS COVERED. CHECKED VISIBLE AREA ONLY / OK	الشاسيه
08 Brake Condition		الفرامل
08.A Brake Pedal	WEAK	دواسة الفرامل
09 Engine Condition		المحرك
09.A Mount	MOUNT RUBBER CRACKED	كرسي
09.B Visual Engine Condition	MINOR OIL LEAK & REFITTED	حالة المحرك النظرى
10 Interior Condition		الحاله الداخليه
10.A AC Condition	NOT WORKING	المكيف
10.B Power Window Switch	FRONT RIGHT SIDE NOT WORKING & REAR RIGHT SIDE NOT WORKING PROPERLY & CURTAIN DAMAGED	مفتاح النافذه
10.C Mirror	LEFT SIDE AUTO FOLDING NOT WORKING & RIGHT SIDE GLASS FADED	المرايا
10.D Sunroof	NOT WORKING	فتحت سقف
10.E Roof Ceiling	LOOSE	بطانه السقف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.