



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>25 Sep 2022, 16:22:59</b>
Transaction Number	<b>64787222 (CC10009)</b>	Queue Number	<b>595937</b>



Chassis Number	<b>1GCNC9EA6BZ300515</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Silverado</b>
Model Year	<b>2011</b>
Color	<b>Black</b>
Mileage	<b>202711 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED , PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
01.C Bonnet	REFITTED	غطاء المحرك
01.D Bumper	MISALIGN	دعامية
01.E Sign of front accident		وجود مؤشر لحادث في المقدمة
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2018	الاطار الامامي
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	JERKING & REFITTED	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A Mirror	CENTER GLASS CRACKED	المرايا
04.B Door Panel	LEFT SIDE LOOSE	لوحة بطانة الباب

DEFECT	REMARKS	
04.C AC Condition	OK	المكيف
04.D Dash Board	PORTION DAMAGED	لوحة القيادة
04.E Power Window Switch	SWITCH COVER LOOSE	مفتاح النافذه
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	SIGN MINOR OIL LEAK & REFITTED	حالة المحرك النظرى
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Shock Absorber	MINOR LEAK	ممتص الصدمات
06.C Arms	LOWER ARM BUSHES CRACKED	ازرع
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Brake Light	LEFT SIDE LOWER BULB NOT WORKING	نور الفرامل
08.C Tail Light	LEFT SIDE CRACKED	الانارة
<b>09 Chassis Condition</b>		<b>الشاصي</b>
09.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED,MINOR BEND ,CHASSIS FRAME RUST PROOFED,GETTING RUSTY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	--
Chassis No :	1GCNC9EA6BZ300515
Vehicle Make :	CHEVROLET
Vehicle Model :	SILVERADO
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	202714 Kms.
Origin : United States	Model Year : 2011
Gear Type : Automatic	Engine Size : 1600 CC
Engine No : nil	Horse : --
Axles No : 2	Power :
No Of : 2	Cylinders : 8
Doors :	No Of Seats : 3
G. V. W. : 2000 Kgs.	Empty Weight : 1600 Kgs.

Certificate Number :	5-TAS-2022-17731223		
Inspection Date :	28-09-2022		
Certificate Print Date :	28-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	12 min 3 sec		
Appointment Ref Number :	--		
Start Time :	8:09	End Time :	8:21
Lane :	03	Token No. :	105
Attempt :	1	Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
12 %	25 %	18 %	0 %
Vehicle on Petrol HC Reading			
34 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Tire change rear both side tires cracks & old 2017	Cracked	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	1600	5300	

Inspection Remarks: chassis & under body components partly rusty & painted body minor scratch & dent

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
6831	VTP Credit Account	17731223	AED 170 Collected on 28/09/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

