



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 Jan 2023, 16:48:06</b>
Transaction Number	<b>69777137 (CC10009)</b>	Queue Number	<b>655660</b>



Chassis Number	<b>JMYLRV93W9J701991</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mitsubishi</b>
Model	<b>Pajero</b>
Model Year	<b>2009</b>
Color	<b>White</b>
Mileage	<b>80383 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
01.B Visual Gear Box Condition	OIL LEAK REFITTED , JERKING	حالة الجير النظرى
01.C Road Test	NOT CHECK	فحص علي الطريق
01.D DIFFERENTIAL	REAR OIL LEAK	الدفرنشل
<b>02 Suspension System</b>		<b>ممتص الصدمات</b>
02.A Arms	LOWER ARM BUSHES CUT	ازرع
02.B Shock Absorber	REAR LEAK	ممتص الصدمات
02.C Ball Joint	BOOT CUT	مفصل كروي
<b>03 Chassis Condition</b>		<b>الشاسي</b>
03.A Chassis	CHASSIS MUDDY CHECKED VISIBLE AREA ONLY /OK	الشاسيه
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Fog light	NOT WORKING & SWITCH LOOSE	كشاف الضباب
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	PORTION CRACKED	حالة المقاعد

DEFECT	REMARKS	
<b>06 Interior Condition</b>		<b>الحاله الداخليه</b>
06.A Dash Board	PORTION DAMAGED	لوحة القيادة
06.B AC Condition	OK & REAR GRAIL PORTION DAMAGED	المكيف
06.C Other	GEAR LEVER INNER COVER MISSING	اخرى
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Roof	PORTION REPAINTED PORTION REPAIRED	السقف
07.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES PORTION RUSTY	الصبغ
07.C Door Handle &Lock	REAR BOTH SIDE OUTER HANDLES NOT WORKING PROPERLY	مقابض الأبواب والأقفال
07.D Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED	مدكار
07.E Sign of back accident		وجود مؤشر لحادث في الخلف
07.F Trunk	REPAIRED REPAINTED	صندوق
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Steering Boot	BOOT CUT	ربلة المقود
08.B Steering Oil	MINOR OIL LEAK	زيت المقود
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2021,	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
<b>10 Engine Condition</b>		<b>المحرك</b>
10.A Mount	MOUNT RUBBER CUT	كرسي
10.B Visual Engine Condition	OIL LEAK REFITTED ABNORMAL NOISY	حالة المحرك النظري
<b>11 Battery Condition</b>		<b>حالة البطارية</b>
11.A Battery bracket	MISSING	حامل البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.