



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>25 Sep 2021, 17:43:46</b>
Transaction Number	<b>43358425 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JMYMRH65WXY000761</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mitsubishi</b>
Model	<b>Pajero</b>
Model Year	<b>2000</b>
Color	<b>Blue</b>
Mileage	<b>180845 N/A</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED EXCEPT ROOF, TRUNK & DENTS ,SCRATCHES, PORTION FADED ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS ,FLOORING , CHASSIS, SUSPENTION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED	الارضية
01.F Bumper	REPAINTED & REPAINTED	دعامية
01.G Roof	REPAINTED & FADED	السقف
01.H Bonnet	REPAINTED	غطاء المحرك
01.I Windshield	FRONT CRACKED	زجاج
01.J Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT REPAIRED OLD GETTING RUSTY	اخرى
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	CHASSIS GETTING RUSTY	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Mount	BUSHES CUT	كرسي
03.B Other	OIL LEAK	اخرى
<b>04 Seats Condition</b>		<b>المقاعد</b>

DEFECT	REMARKS	
04.A Other	OK	اخرى
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Gear Box	GEAR BOX & DEFFRINTAL OIL LEAK	الجير
05.B Gear Box Mount	BUSHES CUT	كرسي الجير
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2016/2017 CRACKED & EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2017 CRACKED	الاطار الخلفي
<b>07 Wipers and Arms</b>		<b>المساحات</b>
07.A Other	WORN OUT	اخرى
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
08.B Other	OK	اخرى
<b>09 Brake Condition</b>		<b>الفرامل</b>
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>10 Suspension System</b>		<b>ممتص الصدمات</b>
10.A Shock Absorber	WEAK & LEAK	ممتص الصدمات
10.B Arms	FRONT BOTH SIDE LOWER ARMS BUSHES CUT & GETTING RUSTY	ازرع
<b>11 Steering Condition</b>		<b>المقود</b>
11.A Steering Boot	BOOT CUT & LEAKING	ربلة المقود
11.B Axle	BOOT CUT & LEAKING	اكسلات
<b>12 Interior Condition</b>		<b>الاجزاء الداخلية</b>
12.A Other	OK	اخرى
12.B Mirror	OK	المرايا
12.C AC Condition	NOT WORKING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.