



Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

Transaction Number : 20551953 Plate Category : PRIVATE

Transaction Date : 10 AUG 2020 10:46:27 Plate Number : 520619 EA

Queue Number : 205339

Chassis Number : MR0FR22G070520619 Manufacturer/Model : TOYOTA/HILUX

Engine Number :

Vehicle Class

Model Year : 2007
LIGHT VEHICLE Vehicle Color : WHITE

Import Doc. Ref.

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفر امل
13.04 - Brake Test	Passed		فحص الفرامل
VISUAL TEST:			
03 Brake System			نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		FRONT BRAKE PAD WORN	قوة فرامل المحور الامامي
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		DOT 0719/WORNOUT	الاطارات الامامية
05 Body			الهيكل
05.02 - Paint		PARTLY DENTT/SCRATCHES /RUSTY	الصبغ
05.04 - Fenders		FRONT REAR BOTH FENDER/FRONT & REAR BOTH DOOR/BOTH RUNNING BOARD REPAIRED/PORTION RUSTY	المدكار
05.05 - Bumpers		FRONT & REAR BUMPER REPAIRED	الدعامية
05.08 - Chassis (Frame)		CHASSIS FRAME & UNDER NEATH PARTLY RUSTY	الشاصية
06 General Items			الاشياء العامة
06.12 - Seats Condition And Seats Fixing		INTERIOR PARTLY WORNOUT/FADED/DIRTY	المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		MINOR OIL LEAK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke		MINOR OIL LEAK	حالة المحرك - الدخان
07 Remarks			ملاحظات
07.04 - Others		66015 KM	ملاحظات اخرى
09 Auction			الفحص الكامل
09.02 - Need Wheel Alignment			بحاجة الى ميز انية العجلات
09.14 - Sign Of Front Accident			أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident			أثر حادث في مؤخرة المركبة
09.25 - Body Repainted			أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.

نهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط سجيل غير مسئولة عن العيوب الخفية