



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Aug 2022, 10:51:54
Transaction Number	53684297 (CC10008)	Queue Number	312309



Chassis Number	2C3CCABG3KH617870
Engine Number	
Vehicle Class	Car
Manufacturer	Chrysler
Model	300
Model Year	2019
Color	Black
Mileage	33664 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	USA Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Air Bag	DAMAGED	وسائد هوائية
01.C Dash Board	CRACKED	لوحة القيادة
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
03 Body		جسم المركبة
03.A Sign of back accident		وجود مؤشر لحادث في الخلف
03.B Other	FRONT FENDER FRAME, RADITOR SUPPORT , BULK HEAD,BUMPER FRAME REPAIRED, BEND	اخرى
03.C Floor	BACK PANEL QUARTER PANEL CONPARTMENT FLOOR REPAIRED.FLOOR COVERED CHECKED ONLY VISIBLE AREA	الارضية
03.D Trunk	REPAIRED REFITTED REPAINTED.	صندوق
03.E Paint	BODY TOTALY REPAINTED REPAIRED , MINOR DENT,SCRATCHES	الصبغ
03.F Bonnet	REFITTED	غطاء المحرك
03.G Sign of front accident		وجود مؤشر لحادث في المقدمة

DEFECT	REMARKS	
03.H Sign of side accident		وجود مؤشر لحادث في الجانب
03.I Doors	ALL DOORS REFITTED REPAINTED REPAIRED.	أبواب
03.J Fenders	FRONTBOTH SIDE REFITTED	مدكار
03.K Roof	REPAIRED REPAINTED.	السقف
04 Chassis Condition		الشاصي
04.A Chassis	FRONT BOTH SIDE CHASSIS END & REAR BOTH SIDE CHASSIS EXTENSION REPAIRED, BEND, DENT	الشاسيه
05 Suspension System		ممتص الصدمات
05.A Suspension Subframe	FRONT & REAR SUSPENSION ASSEMBLY REFITTED.	
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	REFITTED.	حالة الجير النظري
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Seats Condition		المقاعد
07.A Seat Condition	FRONT RIGHT SIDE SEAT COVER DAMAGED	حالة المقاعد
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
09 Engine Condition		المحرك
09.A Visual Engine Condition	REFITTED.	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	2C3CCABG3KH617870
Vehicle Make :	CHRYSLER
Vehicle Model :	300
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	54090 Kms.
Origin : Canada	Model Year : 2019
Gear Type : Automatic	Engine Size : 5700 CC
Engine No : NULL	Horse 292
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2300 Kgs.	Empty 1850 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17329304		
Inspection Date :	02-08-2022		
Certificate Print Date :	02-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Qusais		
Total Time Taken :	6 min 18 sec		
Appointment Ref Number :	--		
Start Time :	20:59	End Time :	21:06
Lane :	06	Token No. :	699
Attempt :	2	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

312 KM	33 L	104 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5700	3600	

Inspection Remarks:

FRONT & REAR BUMPER FRAME // FENDER FRAME / BULKHEAD / RADIATOR FRAME / REAR FENDER FRAME / WHEEL HOUSING QUARTER PANEL REPAIRED .REAR BOTH SIDE FRAME MEMBER REPAIRED STILL BEND HAVING PASSED C C M REPORT W/O # 2022/08/02/14/751

Payment Details

Inspection Performed by 32293	Payment Method Cash	Transaction Number 17329304	Service Fees AED 70 Collected on 02/08/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Jamilah Salem Aamer

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.