



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 Jan 2023, 17:01:06</b>
Transaction Number	<b>55900390 (CC10010)</b>	Queue Number	<b>657732</b>



Chassis Number	<b>JHMCP36788C400959</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Honda</b>
Model	<b>Accord</b>
Model Year	<b>2008</b>
Color	<b>White</b>
Mileage	<b>508635 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT REFITTED	مدكار
01.B Sign of front accident		وجود مؤشر لحادث في المقدمة
01.C Other	MISALIGN,PORTION DAMAGED,FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	اخرى
01.D Paint	BODY REPAIRED,REPAINTED,MINOR DENT ,SCRATCHES ,PORTION FADED	الصبغ
01.E Bonnet	REFITTED	غطاء المحرك
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Roof Ceiling	PORTION LOOSE	بطانه السقف
02.B AC Condition	OK	المكيف
02.C Roof Light	LEFT SIDE DAMAGED	أنارة السقف
02.D Sunroof	NOT WORKING	فتحت سقف
02.E Power Window Switch	MAIN SWITCH PANEL LOOSE,REAR RIGHT SIDE NOT WORKING OWN SWITCH	مفتاح النافذه
<b>03 Chassis Condition</b>		<b>الشاسيه</b>
03.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED,LEFT SIDE DENT ,APRON STUD MOUNT AREA CRACKED .	الشاسيه

DEFECT	REMARKS	
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Rims Condition	RIMS DENT SCRATCHES	حالة الجنوط
04.B Front Tyre	BOTH SIDE 2022	الاطار الامامي
04.C Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	DRIVER SEAT BACK COVER MISSING	حالة المقاعد
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Warning Light	WARNING LIGHT & WARNING MESSAGE ON DISPLAY.	ضوء تحذير
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Shock Absorber	LEAK .	ممتص الصدمات
07.B Arms	LOWER ARM BUSHES CRACKED .	ازرع
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Visual Gear Box Condition	OIL LEAK REFITTED .	حالة الجير النظرى
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Visual Engine Condition	OIL LEAK ,REFITTED .	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.