

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 52569856 (CC10006) Transaction Date

10 May 2022, 16:50:50

Queue Number

312309

Petrol



Chassis Number 2T2ZZMCA6JC114998

Engine Number

Vehicle Class Car

Manufacturer Lexus

Model RX 350

Model Year 2018
Color White

Mileage 79687 Km

Fuel Type

No. Of Cylinders

Specification USA Imported

DEFECT REMARKS

| O1 Body | | جسم المركبة |
|-----------------------------|---|----------------------------|
| 01.A Bonnet | REPAINTED & REFITTED | غطاء المحرك |
| 01.B Fenders | FRONT RIGHT SIDE REFITTED | مدكار |
| 01.C Paint | BODY PORTION REPAIRED , REPAINTED SCRATCHES ON BODY | الصبغ |
| 01.D Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 01.E Other | FRONT RIGHT SIDE FENDER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED | اخري |

| 01.E Other | FRONT RIGHT SIDE FENDER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED | اخري |
|-----------------------------|---|----------------|
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Rear Tyre | BOTH SIDE 2021 | الاطار الخلفي |
| 02.B Front Tyre | BOTH SIDE 2021 | الاطار الامامي |
| 03 Seats Condition | | المقاعد |
| 03.A Seat Belt | REAR BOTH SIDE NOT WORKING | حزام الأمان |
| 04 Engine Condition | | المحرك |

O4.A Visual Engine Condition OK حالة المحرك النظرى

 05 Transmission Condition

| DEFECT | REMARKS | |
|-----------------------------------|---|-------------------|
| 05.A Road Test | NOT CHECH | فحص علي الطريق |
| 05.B Visual Gear Box Condition | ОК | حالة الجير النظرى |
| 06 Interior Condition | | الحاله الداخليه |
| 06.A Air Bag | REAR BOTH SIDE FRONT RIGHT SIDE DAMAGED | وسائد هوائية |
| 06.B AC Condition | ОК | المكيف |
| 06.C Sun Visor | RIGHT SIDE LOOSE | حاجب الشمس |
| 07 Chassis Condition | | الشاصي |
| 07.A Chassis | FRONT RIGHT SIDE CHASSIS END INNER MINOR DENT | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate









Plate Details: Chassis No : 2T2ZZMCA6JC114998 Vehicle Make: LEXUS Vehicle Model: RX 350 Vehicle Class: Light Vehicle **Body Type:** STATION Fuel: Benzene Color: White **Drive Direction:** Left Hand Side Dimensions: (H x W x L) --x--x--**Current Odometer:** 78688 Kms. Origin: Canada Model Year: 2018 Gear Type: Engine Size: 2500 CC Automatic Engine No: NIL Horse Power: 270 Axles No: Cylinders: No Of Doors: 5 No Of Seats: G. V. W.: Empty Weight: 2020 Kgs. 2722 Kas.

| Certificate Number : | 5-SHA-2022-16551491 | | | | |
|--------------------------|---------------------|--|--|--|--|
| Inspection Date : | 07-04-2022 | | | | |
| Certificate Print Date : | 07-04-2022 | | | | |
| Services : | Registration Test | | | | |
| Vehicle Testing Partner: | Shamil | | | | |
| Vehicle Testing Center: | Shamil Al Qusais | | | | |
| Total Time Taken: | | | | | |
| 7 min 19 sec | | | | | |
| Appointment Ref Number : | | | | | |
| Start Time: 13:55 | End Time: 14:02 | | | | |
| Lane: 01 | Token No.: 205 | | | | |
| Attempt: 1 | Prints No : 1 | | | | |

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



Distance per

year





2 AED O.1 ton
Fuel cost per year per year

Parameter Readings

Service brake imbalance on front axle

2%

Service brake imbalance on rear axle 7 %

Parking brake imbalance between LHS and RHS 4 % Vehicle on Petrol CO Reading 0 %

Vehicle on Petrol HC Reading O PPM VOL

Inspection Findings

| Discrepancies | Old Value | New Value | Verified |
|--|-----------|-----------|----------|
| Engine Size Discrepancy in Engine Size | 2500 | 3500 | |
| Doors and Locks Incorrect Number of doors (does not require doc) | 5 | 4 | |

Inspection Remarks: FRONT BULKHEAD RIGHT SIDE FENDER FRAME APRON,OUTER SKIRT WHEEL ARCH REPAIRED.

Payment Details

Inspection Performed by
17778Payment Method
CashTransaction Number
16551491Service Fees
AED 170 Collected on 07/04/2022Parking Slot No
--Service Name
Registration TestAttemptReceived by
Wafa Hasan Zain

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
 ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
 30. يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.