

## **TEST CERTIFICATE**

Site Number
Transaction Number

**03 Chassis Condition** 

**04 Engine Condition** 

03.A Chassis

840-Emirates Auctions 85174423 (CC10006) Transaction Date

27 Nov 2021, 17:31:38

الشاصي

الشاسيه

المحرك

Queue Number

312309



Chassis Number WDDHF5EB3DA740835

Engine Number

Vehicle Class Car

Manufacturer Mercedes

Model E 300

Model Year 2013

Color Beige

Mileage **103128 Km** 

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

**DEFECT** REMARKS

O1 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, BODY MINOR DENT, SCRATCHES	الصبغ
01.B Doors	BOTH SIDE DOOR REPAINTED&FRONT LEFT SIDE REFITIED	أبواب
01.C Fenders	FRONT BOTH SIDE FENDER REPAINTED,PORTION REPAIRED,REFITIED,MISALIGN	مدکار
01.D Bonnet	REPAINTED, PORTION REPAIRED, REFITIED, MISALIGN	غطاء المحرك
O1.E Floor	FRONT LEFT SIDE FLOOR REPAIRED	الارضية
01.F Sign of front accident		وجود مؤشر لحادث في المقدمة
01.G Other	FRONT FULLY ASIMPLY REFITIED	اخري
02 Interior Condition		الحاله الداخليه
02.A AC Condition	ОК	المكيف
02.B Roof Ceiling	PORTION LOOSED	بطانه السقف
02.C Other	CIGARETTES BOX SLIDING COVER MISSING	اخري

FRONT LEFT SIDE CHASSIS REPAIRED

DEFECT	REMARKS	
04.A Engine Condition	NOISY	حالة المحرك
05 Seats Condition		المقاعد
05.A Seat Belt	ОК	حزام الأمان
05.B Seat Condition	ОК	حالة المقاعد
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Gear Box	ОК	الجير
07 Exhaust System		نظام العادم
07.A Modification	CATAYLIC CONVERTER OPEN ,REWELDED	تعديلات
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
09 Tires and Rims Condition		الاطارات
09.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
09.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

## **Test Certificate**











Plate Details: WDDHF5EB3DA740835 Chassis No : Vehicle Make: **MERCEDES** Vehicle Model: E300 Vehicle Class: Light Vehicle **Body Type:** SALOON Fuel: Benzene Color: Piege **Drive Direction:** Left Hand Side Dimensions: (H x W x L) --x--x--**Current Odometer:** 103125 Kms. Origin: Model Year: 2013 Gear Type: **Engine Size:** 4700 CC Automatic Engine No: 272952320... Horse Power: 231 Axles No: Cylinders: No Of Doors: 4 No Of Seats: G. V. W.: Empty Weight: 1300 Kgs. 1900 Kas.

Certificate Number: 5-TAS-2021-15510901 Inspection Date: 22-11-2021 Certificate Print Date : 22-11-2021 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 10 min 51 sec Appointment Ref Number: --Start Time: 13:45 End Time: 13:56 Lane: Token No.: 148

#### Carbon footprint



Thank you! You are environment protector

#### Estimated Vehicle Consumption (Rate in 12 Months)



840 KM Distance per

year

Attempt:

1





Prints No: 1



per year

Fuel cost per vear

0.3 ton Carbon footprint per year

#### **Parameter Readings**

Service brake imbalance on front axle

8 %

Service brake imbalance on rear axle 0%

Parking brake imbalance between LHS and RHS

Vehicle on Petrol CO Reading 0.64 %

# Vehicle on Petrol HC Reading

91 PPM VOL

#### Inspection Findings

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	6	5	

#### **Inspection Remarks:**

FRONT LEFT CHASSIS, REINFORCEMENT, FENDER FRAME, SKIRT, APRON REPAIREDccm ok w/o--20211114-017 tr-30876045

# **Payment Details**

**Inspection Performed by Payment Method** Transaction Number **Service Fees** 33649 Cash 15510901 AED 170 Collected on 22/11/2021 **Parking Slot No** Service Name **Attempt** Received by Sittu Paloth Sreesan Paloth Registration Test

- 🐧 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال .30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.