

Queue Number

2822813

Transaction Date

01 Oct 2026, 16:27:21

Site Name

840 - Emirates Auctions

Transaction Number

86245906 (CC10009) (CC10012)



Vehicle Details

Chassis Number	1GNSK6E05D*****
Specification	GCC Specification
Make	Chevrolet
Model	Tahoe
Model Year	2013
Color	White
Mileage	264065 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION RUSTY , PORTION HOLE	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS THICK RUST PROOFED, NOT VISIBLE	الارضية
01.E Bumper	MISALIGN , PORTION CRACK	دعامية
01.F Roof	PORTION HOLE	السقف
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE B / PILLAR INNER COVER MISSING , BOTH SIDE ROCKER PANEL COVER MISSING	القوائم
01.I Door Handle & Lock	REAR BOTH SIDE HANDLE INNER MISSING	مقابض الأبواب والأقفال

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY RUST PROOFED MUDDY PORTION RUSTY BULGE	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY, WIRING OPEN LOOSE	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT EXTRA COVER PORTION DAMAGED , REAR SEAT MISSING	حالة المقاعد
---------------------	---	--------------

Condition	Remarks	الحالة
05 Transmission Condition الجير		
05.A Gear Box Visual Condition	REFITTED MINOR OIL LEAK GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKD	فحص علي الطريق
06 Tires and Rims Condition الاطارات		
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	HUB COVER MISSING	حالة الجنوط
07 Wipers and Arms المساحات		
07.A Wiper Arm & Blade	REAR DAMAGED	ازرع المساحات والشفرات
08 Brake Condition الفرامل		
08.A Hand Brake	NOT WORKING	فرامل اليد
09 Suspension System ممتص الصدمات		
09.A Arms	BUSHES CUT	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition الحالة الداخليه		
10.A Other	INTERIOR PARTS GETTING RUSTY , (INTERIOR PARTS COVER MISSING)	اخرى
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	REAR NOT WORKING FROM MAIN SWITCH , PANEL , SWITCH MISSING	مفتاح النافذه و الزجاج
10.D Floor Matting	FRONT DAMAGED , REAR MISSING	فرش الأرضيه
10.E Audio	MISSING , REAR SPICKER MISSING	صوتيات
10.F Roof Ceiling	PORTION DAMAGED , GRAB HANDLE MISSING	بطانه السقف
10.G Door Panel	FRONT PORTION DAMAGED , REAR PANEL COVER MISSING	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae