



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Sep 2022, 13:19:58
Transaction Number	98089494 (CC10009)	Queue Number	592238



Chassis Number	4M2EU47E08UJ03291
Engine Number	
Vehicle Class	Car
Manufacturer	Mercury
Model	Mountaineer
Model Year	2008
Color	Maroon
Mileage	353983 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Roof Ceiling	PORTION LOOSE	بطانه السقف
01.B Door Panel	PORTION DAMAGED	لوحة بطانه الباب
01.C AC Condition	LOW COOLING , GRILL DAMAGED	المكيف
01.D Sun Visor	RIGHT SIDE GLASS COVER MISSING	حاجب الشمس
01.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02 Body		جسم المركبة
02.A Trunk	PORTION REPAIRED,REPAINTED,REFITTED	صندوق
02.B Fenders	FRONT FIBER PAINT CANNOT CHECK	مدكار
02.C Paint	BODY PORTION REPAIRED, REPAINTED,MINOR DENT,SCRATCHES & PORTION FADED	الصبغ
02.D Door Handle &Lock	REAR RIGHT SIDE INNER HANDLE DAMAGED	مقابض الأبواب والأقفال
02.E Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED & REAR RIGHT SIDE QUATER PANEL REPAIRED	اخرى
02.F Sign of front accident		وجود مؤشر لحادث في المقدمة
03 Transmission Condition		الجير

DEFECT	REMARKS	
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	OIL LEAK,REFITTED	حالة الجير النظرى
03.C Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	LEFT SIDE 2020 & RIGHT SIDE 2018 CRACKED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2018 & CRACKED	الاطار الخلفي
05 Engine Condition		المحرك
05.A Visual Engine Condition	OIL LEAK,REFITTED	حالة المحرك النظرى
05.B Mount	MOUNT RUBBER CUT	كرسي
05.C Smoke	WHITE SMOKE	دخان
06 Suspension System		ممتص الصدمات
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Other	STABILIZER LINK BOOT CUT	اخرى
06.C Arms	LOWER ARM BUSHES CUT	ازرع
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Seats Condition		المقاعد
09.A Seat Condition	PORTION DAMAGED	حالة المقاعد
10 Chassis Condition		الشاسي
10.A Chassis	FRONT RIGHT SIDE CHASSIS END DENT & LEFT SIDE SLIGHTLY DEND	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	66883152
Chassis No :	4M2EU47E08UJ03291
Vehicle Make :	MERCURY
Vehicle Model :	MOUNTAINEER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Marone
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	353984 Kms.
Origin : United States	Model Year : 2008
Gear Type : Automatic	Engine Size : 4000 CC
Engine No : 8UJ03291	Horse 210
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 7
G. V. W. : 3200 Kgs.	Empty 2200 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17705993		
Inspection Date :	25-09-2022		
Certificate Print Date :	25-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	10 min 56 sec		
Appointment Ref Number :	--		
Start Time :	13:21	End Time :	13:32
Lane :	03	Token No. :	162
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
5 %	1 %	2 %	0.72 %
Vehicle on Petrol HC Reading			
206 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Battery fix battery bracket	Missing	Major
Tire change rear bot side & front right side tires cracks	Cracked	Major
Engine repair engine oil leaking	Oil leaking continuously	Major

Inspection Remarks: front bumper support repaired/front right & rear left side chassis end dent body scratches

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
6831	VTP Credit Account	17705993	AED 170 Collected on 25/09/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيس الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيس المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

