

Queue Number

2822511

Transaction Date

01 Oct 2026, 16:27:16

Site Name

840 - Emirates Auctions

Transaction Number

92276172 (CC10009) (CC10025)



Vehicle Details

Chassis Number	JTEJU9FJ9E*****
Specification	GCC Specification
Make	Toyota
Model	Prado
Model Year	2014
Color	White
Mileage	602556 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAINTED DENTS SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR MUDDY PORTION DENT , ELFT SIDE FRAME SUPPORT BRACKET OPEN	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Roof	MODIFIED HOLE	السقف
01.H Bonnet	REPAINTED PORTION REPAINTED	غطاء المحرك
01.I Other	FRONT BUMPER BULK HEAD CRSH BOX RUSTY HOLES	اخرى
01.J Trunk	REPAINTED PORTION REPAINTED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	MIDDLE BOTH SIDE CHASSIS FRAME DAMAGED RUSTY CRACKED HOLES LOADING POINT RUSTY BULGED, CRACKED	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED SHAKING MISFIRING DEALY STARTING, ABNORMAL NOISY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	PORTION DAMAGED , REAR LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY JERKING,	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2024 , RIGHT SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED RIGHT SIDE CRACK	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR LEAK	ممتص الصدمات
08.B Arms	BUSHES CRACKED	ازرع
08.C Other	REAR RIGHT SIDE CONTROL ARM WITH FRAME GETTING DAMAGED	اخرى
08.D Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخلية
09.A Mirror	CENTER MIRROR MINOR FADED LOOSE	المرايا
09.B AC Condition	NOT WORKING PROPERLY , GRILL PORTION DAMAGED , INTERIOR PARTS RUSTY	المكيف
09.C Roof Light	FRONT PORTION LOOSE	أنارة السقف
09.D Power Window Switch And Glass	RAER RIGHT SIDE SWITCH MAIN NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
09.E Audio	MISSING	صوتيات
09.F Dash Board	PORTION DAMAGED	لوحة القيادة
09.G Door Panel	WORN OUT	لوحة بطانة الباب
09.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae