

Queue Number 2819384

Transaction Date 30 Sep 2026, 16:55:41

Site Name
840 - Emirates AuctionsTransaction Number
49388068 (CC10009) (CC10012)

Vehicle Details

Chassis Number	1GNUKAE03A*****
Specification	GCC Specification
Make	Chevrolet
Model	
Model Year	2010
Color	White
Mileage	255153 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION RUSTY , PORTION HOLE	الصبغ
01.C Bumper	MISALIGN , PORTION CRACK	دعامية
01.D Roof	PORTION HOLE	السقف
01.E Bonnet	REFITTED	غطاء المحرك
01.F Pillars	LEFT SIDE B / PILLAR INNER COVER MISSING , BOTH SIDE ROCKER PANEL COVER MISSING	القوائم
01.G Door Handle & Lock	REAR BOTH SIDE HANDLE INNER MISSING	مقابض الأبواب والأقفال
01.H Vehicle Model	TAHOE	طرز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY DIRTY FULLY RUST PROOFED, GETTING RUSTY PORTION MINOR DENT	الشاسيه
02.B Chassis Number	GETTING RUSTY NOT VISIBLE	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY MUDDY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT EXTRA COVER PORTION DAMAGED , REAR SEAT MISSING	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY, JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	BUSHES CRACKED, LEAK	ممتص الصدمات
08.B Arms	BUSHES CRACKED	ازرع
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
09.B Steering Boot	ON SIDE BOOT OPEN	ربلة المقود
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY , (INTERIOR PARTS COVER MISSING)	اخرى
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	REAR NOT WORKING FROM MAIN SWITCH , PANEL , SWITCH MISSING	مفتاح النافذه و الزجاج
10.D Floor Matting	FRONT DAMAGED , REAR MISSING	فرش الأرضيه
10.E Audio	MISSING , REAR SPICKER MISSING	صوتيات
10.F Dash Board	PORTION DAMAGED , MODIFIED	لوحة القيادة
10.G Roof Ceiling	DAMAGED , GRAB HANDLE MISSING	بطانه السقف
10.H Door Panel	FRONT PORTION DAMAGED , REAR PANEL COVER MISSING	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae