

Queue Number 2899955

Transaction Date 29 Oct 2026, 13:23:43

Site Name
840 - Emirates AuctionsTransaction Number
80046651 (CC10009) (CC10012)

Vehicle Details

Chassis Number	W1KWF8EB1M*****
Specification	Imported
Make	Mercedes
Model	C 300
Model Year	2021
Color	Black
Mileage	24315 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
01.C Doors	LEFT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION DENT	الارضية
01.F Bumper	MISALIGN , SKIRT PORTION PORTION DAMAGED	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE C / PILLAR REPAIRED	القوائم
01.I Trunk	REFITTED , MISALIGN	صندوق
01.J Door Handle & Lock	LEFT SIDE LOCK COVER MISSING	مقابض الأبواب والأقفال
01.K Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAM REPAIRED	وجود مؤشر لحادث في المقدمة
01.L Sign of side accident		وجود مؤشر لحادث في الجانب
01.M Sign of back accident	BACK PANEL QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS WELDED REPAIRED SUSPECT REPLACED, REAR LEFT SIDE EXTENSION OUTER REPAIRED OPEN DETACHED	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

Condition	Remarks	الحالة
03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOIT CHECKED OIL LEAK REFITTED, GETTING RUSTY	الحالة النظرية للمحرك
04 Exhaust System		نظام العادم
04.A Other	REAR MUFFLER DENT	اخرى
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED, GETTING RUSTY, NOT CHECKED	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY , (INTERIOR REFITTED)	اخرى
08.B AC Condition	NOT CHECK	المكيف
08.C Floor Matting	PORTION LOOSE	فرش الأرضية
08.D Roof Ceiling	REPLACED	بطانة السقف
08.E Door Panel	REAR RIGHT SIDE WORN OUT	لوحة بطانة الباب
08.F Air Bag	DAMAGED	وسائد هوائية
08.G Sunroof	CURTAIN SKIRT LOOSE	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae