



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **22 Feb 2022, 18:09:30**  
 Transaction Number **85501728 (CC10006)** Queue Number **312309**



Chassis Number **JN8FY1NY2JX037202**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Nissan**  
 Model **Patrol**  
 Model Year **2018**  
 Color **Black**  
 Mileage **103994 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Pillars	BOTH SIDE DOORS PILLAR, ROOF RAIL, ROOF REPAIRED	القوائم
01.B Bumper	REPAINTED	دعامة
01.C Sign of front accident		وجود مؤشر لحادث في المقدمة
01.D Sign of side accident		وجود مؤشر لحادث في الجانب
01.E Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.F Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
01.G Fenders	PORTION REPAIRED,REPAINTED	مدكار
01.H Doors	PORTION REPAIRED,REPAINTED	أبواب
01.I Trunk	REFITTED	صندوق
01.J Other	FOR RECHECK PROPERLY NEED TO REMOVE PIILARS, ROCKER PANEL , ROOF CILING& BEEDING COVER	اخرى
01.K Floor	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	الارضية
<b>02 Exhaust System</b>		<b>نظام العادم</b>
02.A Other	MODIFIED&CATAYLIC CONVERTER MISSING	اخرى
02.B Modification	MODIFIED	تعديلات

DEFECT	REMARKS	
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق
03.C DIFFERENTIAL	FRONT MINOR LEAK	الدفرنشل
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	OK	حالة المحرك النظري
<b>05 Chassis Condition</b>		<b>الشاصي</b>
05.A Chassis	REAR BOTH SIDE ARCH CHASSIS MINOR BULDGE & CHASSIS FRAME RUST PROOFED	الشاسيه
<b>06 Seats Condition</b>		<b>المقاعد</b>
06.A Seat Condition	MIDDLE SEATS LOOSE & RAW SEAT MISSING	حالة المقاعد
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>08 Interior Condition</b>		<b>الحاله الداخليه</b>
08.A AC Condition	OK	المكيف
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
09.B Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
09.C Tail Light	FRONT BOTH SIDE PARK LIGHT NOT WORKING	الانارة

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Transfer Certificate :	66189684
Chassis No :	JN8FY1NY2JX037202
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	103995 Kms.
Origin :	Japan
Model Year :	2018
Gear Type :	Manual
Engine No :	TB48 110502
Engine Size :	4800 CC
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	7
G. V. W. :	2900 Kgs.
Empty Weight :	2035 Kgs.

Certificate Number :	5-TAS-2022-16242442
Inspection Date :	27-02-2022
Certificate Print Date :	27-02-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	10 min 41 sec
Appointment Ref Number :	--
Start Time :	16:22
End Time :	16:33
Lane :	03
Token No. :	244
Attempt :	1
Prints No :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
8 %	17 %	21 %	0 %
Vehicle on Petrol HC Reading			
0 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Tinted	Reflective	Major

## Inspection Remarks:

all door pillar & roof rail repaired // old //FRONT BULKHEAD,LEFT FENDER FRAME REPAIRED/REAR BOTH SIDE CHASSIS MINOR BULGED & FRONT LEFT SIDE CHASSIS END DENT

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
71051	VTP Credit Account	16242442	AED 170 Collected on 27/02/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

**i** This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

**i** Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

