

Queue Number	2836153	Transaction Date	05 Oct 2026, 12:32:29
Site Name	840 - Emirates Auctions	Transaction Number	83416543 (CC10010) (CC10010)
		Vehicle Details	
		Chassis Number	WBAPA91064*****
		Specification	GCC Specification
		Make	BMW
		Model	X3
		Model Year	2004
		Color	Silver
		Mileage	N/A Km
		Fuel Type	Petrol
		Transmission Type	
		No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY	الارضية
01.D Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.E Bonnet	SHOCK WEAK .	غطاء المحرك
02 Chassis Condition		
02.A Chassis	CHASSIS COVERED OILY MUDDY ,PORTION MINOR DENT ,CHECKED ONLY VISIBLE AREA .	الشاسيه
03 Engine Condition		
03.A Mount	BUSHES CRACKED .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
04 Seats Condition		
04.A Seat Condition	DIRTY LOOSE.	حالة المقاعد
05 Transmission Condition		
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY,OIL PAN DENT.	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020 EXPIRED CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 EXPIRED CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK,RIGHT SIDE CRACKED .	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACKED .	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY .	دسك وطنايبر الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحالة الداخلية
11.A Other	INTERIOR PARTS GETTING RUSTY , (SIGN OF FLOODED)	اخرى
11.B Mirror	LOOSE FADED.	المرآيا
11.C AC Condition	NOT CHECKED.	المكيف
11.D Dash Board	PORTION LOOSE CENTER CONSOLE ASSEMBLY DAMAGED .	لوحة القيادة
11.E Roof Ceiling	LOOSE.	بطانه السقف
11.F Odometer reading	NOT CHECKED .	قراءة عداد المسافات
11.G Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.H Air Bag	STEERING AIR BAG DAMAGED .	وسائد هوائية
11.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae