



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	13 May 2022, 11:51:54
Transaction Number	43937263 (CC10006)	Queue Number	312309



Chassis Number	1FMJU1K50BEF49304
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Expedition
Model Year	2011
Color	Silver
Mileage	145002 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Engine Condition		المحرك
01.A Mount	BOTH SIDE MOUNT RUBBER CRACKED	كرسي
01.B Visual Engine Condition	MINOR OIL LEAK , REFITTED	حالة المحرك النظري
02 Body		جسم المركبة
02.A Fenders	LEFT SIDE BOTH PORTION REPAIRED,REPAINTED	مذكار
02.B Doors	LEFT SIDE BOTH PORTION REPAIRED,REPAINTED	أبواب
02.C Trunk	PORTION REPAIRED & REPAINTED	صندوق
02.D Bonnet	SHOCK WEAK & REPAINTED ,REFITTED	غطاء المحرك
02.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES & PORTION RUSTY	الصبغ
02.F Sign of front accident		وجود مؤشر لحادث في المقدمة
02.G Bumper	FRONT BUMPER FRAME BEND	دعامية
02.H Other	FROTN BUMPER FRAME BULK HEAD , RADIATOR SUPPORT REPAIRED	اخرى
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي

DEFECT	REMARKS	
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
04.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
04.D Propeller Shaft	REFITTED , JOINT AREA LEAK	ناقل الحركة
05 Battery Condition		حالة البطارية
05.A Battery bracket	MISSING	حامل البطارية
06 Suspension System		ممتص الصدمات
06.A Arms	BUSHES CRACKED	ازرع
06.B Shock Absorber	REAR LEAK	ممتص الصدمات
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08 Lights		الاضاءة
08.A Tail Light	REAR BOTH SIDE DAMAGED	الانارة
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08.C Fog light	BOTH SIDE NOT WORKING	كشاف الضباب
08.D Head Light	BOTH SIDE HIGH BEAM NOT WORKING	الاضاءة الرئيسية
09 Interior Condition		الحالة الداخليه
09.A Steering Wheel and control buttons	HORN NOT WORKING	عجلة القيادة وازرار التحكم
09.B AC Condition	NOT COOLING	المكيف
10 Chassis Condition		الشاسي
10.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED STILL MINOR DENT	الشاسيه
11 Exhaust System		نظام العادم
11.A Modification	CATALYTIC CONVERTER REWELDED, NOISY	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	66486006
Chassis No :	1FMJU1K50BEF49304
Vehicle Make :	FORD
Vehicle Model :	EXPEDITION
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	145005 Kms.
Origin :	United States
Model Year :	2011
Gear Type :	Automatic
Engine Size :	5400 CC
Engine No :	BEF49304
Horse Power :	310
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	8
G. V. W. :	Empty Weight : 2629 Kgs. 3200 Kgs.

Certificate Number :	5-TAS-2022-16774317
Inspection Date :	17-05-2022
Certificate Print Date :	18-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	15 min 38 sec
Appointment Ref Number :	--
Start Time :	17:16
End Time :	17:32
Lane :	01
Token No. :	323
Attempt :	1
Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
3 %	4 %	6 %	0 %
Vehicle on Petrol HC Reading			
7 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Stop lamps	Bulb busted	Major
Arm, mounting, bushes replace front both side upper arm ball joint	Defective or worn out arm ball joint	Major
Reversing lamps	Defective	Major
Park and Tail lamps fix front&rear all	Bulb busted	Major
Tire replace all tires/expierd&crack	Date of manufactured tampered or expired	Major
Rear registration plate lamps	Bulb busted	Major

Inspection Remarks:

Front bumper,bulk head,fender,wheel housing repaired,minor transmission oil leak. front right side chassis end old repaired

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
34944 8008085 59466 59466	Cash	16774317	AED 170 Collected on 18/05/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

