



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	03 Jul 2022, 15:46:48
Transaction Number	67898919 (CC10006)	Queue Number	312309



Chassis Number	JT8BH28F1X0156966
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	LS400
Model Year	1999
Color	Black
Mileage	404184 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
01.B Indicator & Hazard light	FRONT RIGHT SIDE INDICATOR NOT WORKING	الاشارات
02 Interior Condition		الحالة الداخليه
02.A AC Condition	NOT COOLING	المكيف
02.B Mirror	LEFT SIDE ADJUSTMENT NOT WORKING	المرايا
02.C Sunroof	NOT WORKING PROPERLY	فتحت سقف
02.D Odometer reading	ODOMETER PORTION FADED	قراءة عداد المسافات
03 Body		جسم المركبة
03.A Pillars	BOTH SIDE C/PILLAR DOOR POST REPAIRED,REPAINTED	القوائم
03.B Paint	BODY TOTALY REPAIRED,REPAINTED,MINOR DENT SCRATCHES	الصبغ
03.C Sign of front accident		وجود مؤشر لحادث في المقدمة
03.D Sign of back accident		وجود مؤشر لحادث في الخلف
03.E Sign of side accident		وجود مؤشر لحادث في الجانب
03.F Floor	RIGHT SIDE RUNNING BOARD FRONT FLOOR JOINT REPAIRED STILL DENT	الارضية

DEFECT	REMARKS	
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
06 Engine Condition		المحرك
06.A Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري
06.B Mount	MOUNT RUBBER CRACKED	كرسي
06.C Other	ENGINE BELT BROKEN	اخرى
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07.B Other	STABILIZER LINK BOOT CUT	اخرى
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Steering Oil	MINOR OIL LEAK	زيت المقود
08.B Tie Rod End	BOOT CUT	مؤخرة الروداد
08.C Steering Boot	LEAK	ربلة المقود
09 Chassis Condition		الشاسي
09.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED REAR BOTH SIDE CHASSIS SPARE WHEEL HOUSE SUSPECT REPALCED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	J 69768 Dubai Private
Chassis No :	JT8BH28F1X0156966
Vehicle Make :	LEXUS
Vehicle Model :	LS400
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	650471 Kms.
Origin : Japan	Model Year : 1999
Gear Type : Automatic	Engine Size : 4000 CC
Engine No : NIL	Horse 284
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 2250 Kgs.	Empty 1841 Kgs.
	Weight :

⚠ Retest can be done only in Dubai

Certificate Number :	5-TAS-2022-17357211
Inspection Date :	07-08-2022
Certificate Print Date :	07-08-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	14 min 3 sec
Appointment Ref Number :	--
Start Time : 14:48	End Time : 15:02
Lane : 02	Token No. : 212
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle 2 %	Service brake imbalance on rear axle 12 %	Parking brake imbalance between LHS and RHS 30 %	Vehicle on Petrol CO Reading 0.06 %
Vehicle on Petrol HC Reading 0 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Engine repair excessive smoke	Excessive oil smoke	Major
Engine replace drive belts/cracked	Others (Major)	Major
Engine	Oil leaking continuously	Major
Battery fix bracket	Unsecure	Major
Suspension kit replace front&rear suspension bushes	Others (Major)	Major

Discrepancies

Discrepancies	Old Value	New Value	Verified
Incorrect information about GCC specifications with No Document	Incorrect information about GCC	Yes	No

Inspection Remarks:

Front bulk head,radiator frame,rear panel,rear both side quarter panel,rear right frame member extension,both side C pillar,fender,wheel arch repaired.old

Payment Details

Inspection Performed by 35063	Payment Method Cash	Transaction Number 17357211	Service Fees AED 170 Collected on 07/08/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any



purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.