



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	31 Mar 2022, 17:51:12
Transaction Number	59450108 (CC10008)	Queue Number	312309



Chassis Number	JN8AY2NYXF9135082
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2015
Color	White
Mileage	255006 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
01.B Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
02 Interior Condition		الحالة الداخليه
02.A AC Condition	OK	المكيف
02.B Mirror	BOTH SIDE FOLDING & ADJUSTMENT NOT WORKING POROERLY	المرايا
02.C Dash Board	LEATHER REPLACED	لوحة القيادة
03 Body		جسم المركبة
03.A Doors	FRONT BOTH SIDE PORTION REPAIRED, REPAINTED & REAR BOTH SIDE REPAINTED	أبواب
03.B Bumper	REPAINTED & MISALIGN	دعامية
03.C Trunk	PORTION REPAIRED, REPAINTED	صندوق
03.D Fenders	RIGHT SIDE BOTH PORTION REPAIRED, REPAINTED & LEFT SIDE BOTH REPAINTED, FRONT REFITTED	مدكار
03.E Bonnet	REPAINTED & REFITTED	غطاء المحرك
03.F Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى

DEFECT	REMARKS	
03.G Paint	BODY REPAINTED EXCEPT ROOF& PORTION REPAIRED , MINOR DENT, SCRATCHES,BODY SHAPE CHANGED TO NEW MODEL	الصبغ
03.H Floor	UNDER FLOOR & CHASSIS FRAME RUST PROOFED	الارضية
03.I Sign of front accident		وجود مؤشر لحادث في المقدمة
04 Suspension System		ممتص الصدمات
04.A Arms	FRONT LOWER ARM BUSH CUT	ازرع
05 Engine Condition		المحرك
05.A Visual Engine Condition	REFITTED	حالة المحرك النظرى
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Visual Gear Box Condition	REFITTED	حالة الجير النظرى
07 Tires and Rims Condition		الاطارات
07.A Rear Tyre	BOTH SIDE 2021/2022	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2021	الاطار الامامي
08 Chassis Condition		النشاصي
08.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED,STILL BEND	النشاصيه
09 Steering Condition		المقود
09.A Steering Oil	MINOR OIL LEAK	زيت المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	JN8AY2NYXF9135082
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	255006 Kms.
Origin :	Japan
Model Year :	2015
Gear Type :	Automatic
Engine Size :	3500 CC
Engine No :	VK560094...
Horse Power :	400
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	8
G. V. W. :	Empty Weight : 2200 Kgs. 2500 Kgs.

Certificate Number :	5-TAS-2022-16550675
Inspection Date :	07-04-2022
Certificate Print Date :	07-04-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	14 min 27 sec
Appointment Ref Number :	--
Start Time :	12:29
End Time :	12:43
Lane :	02
Token No. :	138
Attempt :	1
Prints No :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

60 KM	7 L	12 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 14 %	Service brake imbalance on rear axle 14 %	Parking brake imbalance between LHS and RHS 33 %	Vehicle on Petrol CO Reading 0.01 %
---	--	---	--

Vehicle on Petrol HC Reading
3 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	5600	

Inspection Remarks:

front left side chassis repaired with c.c.m report attached in old transaction/work order #2022-03-21-14/ front left side fender frame & wheel housing /bulkhead repaired

Payment Details

Inspection Performed by 59460	Payment Method Cash	Transaction Number 16550675	Service Fees AED 170 Collected on 07/04/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

