

01 Tires and Rims Condition

TEST CERTIFICATE

للاطاليات

Site Number **840-Emirates Auctions** 11 Mar 2023, 13:03:05 Transaction Date

Transaction Number 75876569 (CC10010) Queue Number 686841



Chassis Number **WDCYC7CF7EX218481**

Engine Number

Vehicle Class Car

Manufacturer Mercedes

Model **G 63 AMG**

Model Year 2014 Color White

87571 Km

Fuel Type **Petrol**

No. Of Cylinders

Mileage

Specification **GCC Specification**

DEFECT REMARKS

or rice and raine condition		الاطارات
01.A Front Tyre	BOTH SIDE 2021,	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
02 Engine Condition		المحرك
O2 A Mount	PIGHT SIDE MOUNT BUSHES CRACKED	<

02.A Mount RIGHT SIDE MOUNT BUSHES CRACKED. كرسي 02.B Visual Engine Condition SIGN OF OIL WET, حالة المحرك النظرى

جسم المركبة 03 Body

03.A Paint BODY PORTION REPAINTED, PORTION REPAIRED, MINOR الصبغ **DENT, SCRATCHES**

03.B Floor UNDER BODY, SUSPENSION PARTS RUSTPROOFED الارضية

COATED.

FRONT BOTH SIDE REPAINTED PORTION REPAIRED 03.C Fenders مدكار

,REFITTED

03.D Bonnet REPAINTED PORTION REPAIRED, REFITTED غطاء المحرك

03.E Other FRONT BULKHEAD , BUMPER BRACKET RADIATOR SUPPORT. اخري

FENDER FRAME REPAIRED. RIGHT SIDE BULKHEAD MINOR

DETACHED..

03.F Sign of front accident وجود مؤشر لحادث في المقدمة

DEFECT		
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	SIGN OF OIL WET.	حالة الجير النظرى
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C DIFFERENTIAL	FRONT BOTH SIDE ROMANO JOINT MINOR OIL LEAK.	الدفرنشل
05 Chassis Condition		الشاصي
05.A Chassis	FRONT LEFT SIDE CHASSIS INNER MINOR BULGED.CHASSIS FRAME RUSTPROOF COATED.	الشاسيه
06 Suspension System		ممتص الصدمات
06.A Shock Absorber	MOUNTING BUSHES CRACKED.	ممتص الصدمات
07 Steering Condition		المقود
07.A Tie Rod End	BOOT CUT.	مؤخرة الرودات
08 Interior Condition		الحاله الداخليه
08 Interior Condition 08.A AC Condition	ОК	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate









Plate Details:			-			
Chassis No:		W	DCYC7CF7EX218	3481		
Vehicle Make :		М	ERCEDES			
Vehicle Model	:	G	63			
Vehicle Class:			Light Vehicle			
Body Type:			STATION			
Fuel:		Benzene				
Color:		White				
Drive Direction:						
Dimensions : (I	HxWxL)		· x x			
Current Odome	ter:	87	7572 Kms.			
Origin: A	ustria		Model Year:	2014		
Gear Type: A	utomatic		Engine Size:	4700 CC		
Engine No: 15	79846004		Horse			
Axles No: 2			Power :			
No Of 4			Cylinders:	8		
Doors :			No Of Seats:	5		
G. V. W. : 33	350 Kgs.		Empty Weight:	2548 Kgs.		

Certificate Number: 5-TAS-2023-19022089 Inspection Date: 14-03-2023 Certificate Print Date : 14-03-2023 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 12 min 50 sec **Appointment Ref** Number: Start 10:18 **End Time:** 10:31 Time: Token No.: 126 Lane: 01 Prints No: 1 Attempt: 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



Distance per

year

751 L
Fuel consumed
per year



2584 AED
Fuel cost per year

year

1.8 ton
Carbon footprint
per year

Parameter Readings

Service brake imbalance on front axle 0 %

Service brake imbalance on rear axle 0 %

Parking brake imbalance between LHS and RHS 2%

Vehicle on Petrol CO Reading 0%

Inspection Findings

Vehicle on Petrol HC

Reading 6 PPM VOL

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	4700	5500	

Inspection Remarks: minor front diffedrential oil leak/ rear seat belt cover fix properly minor

Payment Details

Inspection Performed by
3104Payment MethodTransaction NumberService Fees3104VTP Credit Account19022089AED 170 Collected on 14/03/2023Parking Slot NoService NameAttemptReceived by--Registration Test1Bajurdeen Abdul Gafoor

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
 ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
 30. يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.