

Queue Number 2902351

Transaction Date 23 Oct 2026, 16:52:28

Site Name
840 - Emirates AuctionsTransaction Number
90830294 (CC10013) (CC10011)

Vehicle Details

Chassis Number	VF38D5FC3H*****
Specification	GCC Specification
Make	Peugeot
Model	508
Model Year	2017
Color	Black
Mileage	188667 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION COVERED DENT DIRTY	الارضية
01.E Bumper	MISALIGN,MINOR DENT SCRATCHES	دعامية
01.F Roof	REPAINTED	السقف
01.G Bonnet	STAY SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED LOGO MISSING,STAY SHOCK NOT WORKING	صندوق
01.I Sign of back accident	BACK PANEL , COMPARTMENT AREA REPAIRED DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS OILY MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL PAN DENT , MINOR OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DIRTY	حالة المقاعد
---------------------	-------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , HOUSING BOLT MISSING , PARTS GETTING RUSTY , OIL WET , MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Hand Brake	SWITCH PORTION FADED	فرامل اليد
08.B Disc&Drum	GETTING RUSTY	دسك وطنايير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
10.B AC Condition	NO COOLING	المكيف
10.C Roof Light	SWITCH GETTING WORN OUT	أنارة السقف
10.D Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH NOT WORKING LOOSE	مفتاح النافذه و الزجاج
10.E Dash Board	RIGHT SIDE CUP HOLDER NOT CLOSE	لوحة القيادة
10.F Door Panel	PORTION GETTING WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT,CONTROL SWITCH FADED	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10.I Engine Start Button	FADED,REMOTE PART MISSING	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae