CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2942195
Transaction Date	05 Nov 2026, 12:22:24
Site Name	840 - Emirates Auctions
Transaction Number	28343137 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WBABS51040*******
Specification	Imported
Make	BMW
Model	330 CI
Model Year	2000
Color	Silver
Mileage	103915 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR FULLY MUDDY RUST PROOFED PORTION DENT,FRONT CHASSIS COVERED	الارضية
01.D Bumper	MISALIGN,COVER HOOK MISSING	دعامية
01.E Roof	CONVERTIBLE ROOF FABRIC NOT WORKING	السقف
01.F Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY COVERED PORTION MINOR DENT/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY SHAKING DELAY STARTING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY,COVER PORTION DAMAGED	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	MUFFLER CRACKED DENT	اخري
06 Transmission Condition		الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	OIL LEAK REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		**الاطارات**
07.A Front Tyre	BOTH SIDE 2019 EXPIRED	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2019 EXPIRED	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		**الاضاءة**
08.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		**ممتص الصدمات**
09.A Shock Absorber	MODIFIED	ممتص الصدمات
09.B Other	BODY LEVEL LOW,	اخري
09.C Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		**الحاله الداخليه**
10.A Other	CENTER CUP CONSOLE BOX DAMAGED	اخري
10.B Mirror	LEFT SIDE FOLDING NOT WORKING PROPERLY	المرايا
10.C AC Condition	OK	المكيف
10.D Power Window Switch And Glass	REAR LEFT SIDE NOT WORKING	مفتاح النافذه و الزجاج
10.E Audio	NOT WORKING	صوتيات
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae