

Queue Number 2844327

Transaction Date 07 Oct 2026, 13:18:37

Site Name
840 - Emirates AuctionsTransaction Number
32076998 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WDDUG8FB3E*****
Specification	Imported
Make	Mercedes
Model	S 550
Model Year	2014
Color	Black
Mileage	123597 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE , REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Floor	FLOOR CHASSIS NOT VISIBLE	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.G Trunk	REPAINTED PORTION REPAIRED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	FRONT BOTH SIDE BACK COVER LOOSE , REAR CENTER COVER LOCK COVER LOOSE	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	RIGHT SIDE 2023 CRACK , LEFT SIDE DATE NOT VISIBLE , CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY , INTERIOR REFITTED	اخرى
08.B AC Condition	OK	المكيف
08.C Power Window Switch And Glass	REAR RIGHT SIDE NOT WORKING , SWITCH MISSING	مفتاح النافذه و الزجاج
08.D Dash Board	LEATHER PORTION LOOSE , PANEL PORTION LOOSE	لوحة القيادة
08.E Roof Ceiling	PORTION LOOSE	بطانه السقف
08.F Sun Visor	LEFT SIDE MIRROR COVER MISSING	حاجب الشمس
08.G Door Panel	WORN OUT	لوحة بطانة الباب
08.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.I Engine Start Button	REMOTE KEY MISSING	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae