CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2963000
Transaction Date	09 Nov 2026, 15:52:37
Site Name	840 - Emirates Auctions
Transaction Number	66976026 (CC10009) (CC10011)



Vehicle Details

Chassis Number	JT3HJ09JXY*******
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2000
Color	White
Mileage	583204 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,EXCEPT ROOF,MINOR DENTS SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS FULLY MUDDY GETTING RUSTY PORTION DENT,PORTION REPAIRED	الارضية
01.E Bumper	MINOR SCRATCHES,GRILL LOOSE	دعامية
01.F Windshield	SPOT CRACK	زجاج
01.G Bonnet	REFITTED SHOCK WEAK	غطاء المحرك
01.H Pillars	LEFT SIDE B/PILLAR INNER COVER LOOSE,C/PILLAR OUTER PANEL REPAINTED PORTION REPAIRED	القوائم
01.I Trunk	TAILGATE REFITTED,INNER COVER PART MISSING	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS GETTING RUSTY PORTIONMINOR DENT OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	OIL LEAK OPEN REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**

Condition	Remarks	الحالة
04.A Seat Belt	FRONT BOTH SIDE BRACKET COVER PART MISSING	حزام الأمان
04.B Seat Condition	PORTION DAMAGED EXTRA COVER & REAR SEATS MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	CUT REWELDED	اخري
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	OIL LEAK OPEN REFITTED MODIFIED	الحالة النظريه للجير
06.B Gear Box Mount	MOUNT MODIFIED	كرسي الجير
06.C Road Test	NOT CHECKED	فحص علي الطريق
06.D Clutch	HEAVY	القابض
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
08 Lights		الاضاءة
08.A Tail Light	MINOR CRACK	الضوء الخلفي
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CUT	ازرع
09.C Other	SUSPENSION GETTING RUSTY	اخري
09.D Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Steering Oil	MINOR OIL LEAK	زيت المقود
10.B Tie Rod End	BOOT CUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	COOL BOX NOT WORKING, INNER PARTS GETTING RUSTY	اخري
11.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY,CENTER VIEW MIRROR GETTING FADED	المرايا
11.C AC Condition	OK,GRILL PORTION DAMAGED	المكيف
11.D Roof Light	FRONT PANEL LOOSE	أنارة السقف
11.E Power Window Switch And Glass	MAIN SWITCH PANEL LOOSE,REAR BOTH SIDE NOT WORKING FROM MAIN SWITCH PANEL	مفتاح النافذه و الزجاج
11.F FLoor Matting	PORTION DAMAGED	فرش الأرضيه
11.G Dash Board	PORTION WORN OUT LOOSE	لوحة القياده
11.H Roof Ceiling	PORTION DAMAGED WORN OUT	بطانه السقف
11.I Door Panel	PORTION DAMAGED WORN OUT	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae