

Queue Number 2861551

Transaction Date 12 Oct 2026, 13:41:20

Site Name
840 - Emirates AuctionsTransaction Number
54626743 (CC10010) (CC10010)

Vehicle Details

Chassis Number 6T1BE42K49*****
 Specification GCC Specification
 Make Toyota
 Model Camry
 Model Year 2009
 Color Silver
 Mileage N/A Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED PORTION GETTING RUSTY FADED MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS MUDDY	الارضية
01.D Bumper	MISALIGN ,SCRATCHES, PORTION DAMAGED	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME ,FENDER FRAME , RADIATOR SUPPORT BULK HEAD ,CROSS MEMBER INNER FENDER FRAME REPAIRED .	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSI COVERED ,OILY MUDDY ,CHCKED ONLY VISIBLE AREA /OK.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CUT .	كرسي
03.B Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECK REFITTED OIL LEAK ,PARTS RUSTY .	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	DIRTY PORTION LOOSE.	حالة المقاعد
---------------------	----------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK ,PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	--	----------------------

Condition	Remarks	الحالة
05.B Gear Box Mount	BUSHES RACKED .	كرسي الجير
05.C Road Test	NOT CHECKED .	فحص علي الطريق
06 Lights		الاضاءة
06.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY .	دسك و طناير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED.	اخرى
10.B AC Condition	NOT CHECKED .	المكيف
10.C Dash Board	MELTED PORTION CRACKED.	لوحة القيادة
10.D Roof Ceiling	PORTION LOOSE , GRAB HANDLE MISSING.	بطانة السقف
10.E Sun Visor	LOOSE.	حاجب الشمس
10.F Odometer reading	NOT CHECKED .	قراءة عداد المسافات
10.G Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

