

Queue Number 2874392

Transaction Date 16 Oct 2026, 16:45:08

Site Name
840 - Emirates AuctionsTransaction Number
25627242 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WDB2200731*****
Specification	Imported
Make	Mercedes
Model	S 55 AMG
Model Year	2002
Color	Blue
Mileage	93787 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED RUSTY	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR COVERED MUDDY DIRTY / FOR FULL INSPECTION MAKE STEAM WASH REMOVE INNER FENDER COVER FOR RECHECK	الارضية
01.D Bumper	MISALIGN,PORTION DENT SCRATCHES,GRILL LOOSE	دعامية
01.E Windshield	REAR CURTAIN NOT OPEN PROPERLY	زجاج
01.F Pillars	INNER COVER LOOSE	القوائم
01.G Vehicle Model	AS VIN DECODER 2001	طراز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	INTAKE AIR PIPE PORTION CRACK	اخرى
03.B Engine Visual Condition	MINOR OIL LEKA , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION DAMAGED,FRONT RIGHT SEAT SIDE COVER PORTION DAMAGED,ADJUSTMENT NOT WORKING PROPERLY,FRONT LEFT NECK REST ADJUSTMENT NOT WORKING	حالة المقاعد
---------------------	---	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST SYSTEM MODIFIED	تعديلات
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Propeller Shaft	FLANGE RUBBER DRY CRACK	ناقل الحركة
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rims Condition	MINOR SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	SIGN OF LEAK	ممتص الصدمات
09.B Arms	ARM BUSHES DRY CRACK	ازرع
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE BOX COVER WORN OUT,INTERIOR PORTION MODIFIED PARTS REFITTED GETTING RUSTY	اخرى
10.B Mirror	BOTH SIDE LOOSE AUTO FOLDING NOT WORKING SWITCH LOOSE,CENTER VIEW MIRROR LOOSE	المرآيا
10.C AC Condition	OK,GRILL PORTION DAMAGED	المكيف
10.D Dash Board	GRILL PORTION DAMAGED,LEATHER PORTION LOOSE	لوحة القيادة
10.E Roof Ceiling	PORTION LOOSE	بطانة السقف
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Sunroof	NOT WORKING PROPERLY	فتحت سقف
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص

only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae