

Queue Number 2797460

Transaction Date 25 Sep 2026, 12:19:56

Site Name
840 - Emirates AuctionsTransaction Number
19597267 (CC10010) (CC10011)

Vehicle Details

Chassis Number	1ZVBP8AM7D*****
Specification	Imported
Make	Ford
Model	Mustang
Model Year	2013
Color	Grey
Mileage	68885 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED,RIGHT PORTION DAMAGED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED , DENTS SCRATCHES,PORTION GETTING RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
01.D Floor	UNDER FLOOR PORTION MINOR DENT . RIGHT SIDE RUNNING BOARD COVER LOOSE.	الارضية
01.E Bumper	MISALIGN , PORTION CRACK , FIXED BY SCREW	دعامية
01.F Windshield	FRONT SPOT DENT	زجاج
01.G Bonnet	REFITTED , MISALIGN	غطاء المحرك
01.H Pillars	RIGHT SIDE ROCKER PANEL COVER LOOSE	القوائم
01.I Trunk	REFITTED MISALIGN , CHROME STRIP LOOSE , LOGO FADED	صندوق
01.J Sign of front accident	FRONT ASSEMBLY REFITTED ,	وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL ,QUARTER PAANEL ,COMPARTMENT PORTION REPAIRED.	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHECKED VISIBLE AREA /OK.	الشاسيه
--------------	---------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	COMPONENT PARTS RUSTY ,SIGN OF COOLANT LEAKING.	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Belt	BOTH SIDE GUIDE HOLDER DAMAGE	حزام الأمان
----------------	-------------------------------	-------------

Condition	Remarks	الحالة
04.B Seat Condition	FRONT LEFT SIDE SEAT ADJUSMENT HANDLE PORTION CRACK PART MISSING	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	REAR BOTH SIDE CUT /REWELDED.	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	GET JERKING ,COMPONENT PARTS GETTING RUSTY	الحالة النظره للجير
06.B DIFFERENTIAL	REAR OIL LEAK.	الدفرنشل
06.C Road Test	NOT CHECKED .	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025 , RIGHT SIDE MINOR CUT	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS GETTING FADED , RIGHT SIDE DAMAGE REPAIRED , BRACKET DAMAGE	الاضاءة الرئيسية
08.B Tail Light	RIGHT SIDE CRACK	الضوء الخلفي
08.C Warning Light	WARNING LIGHTS HIDE BY INSTRUMENT CLUSTER.	ضوء تحذير
09 Brake Condition		الفرامل
09.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
09.B Hand Brake	WEAK.	فرامل اليد
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK ,WEAK .	ممتص الصدمات
10.B Arms	BUSHES CRACKED .	ازرع
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
11.B Mirror	CENTER MIRROR FADED	المرايا
11.C AC Condition	OK	المكيف
11.D Power Window Switch And Glass	RIGHT SIDE SWICTH LOOSE NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
11.E Dash Board	PORTION WORN OUT	لوحة القيادة
11.F Door Panel	PORTION WORN OUT FABRIC MISSING	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Radiator Hose	TOP HOSE BULGED CRACKED ,COOLANT LEAK.	خرطوم المبرد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae