CAR CHECK

# شهادة فحص مركبة
# Vehicle Test Certificate

| | |
|---|---|
| Queue Number | 2978259 |
| Transaction Date | 12 Nov 2026, 15:45:29 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 76289891 (CC10008) (CC10011) |




## Vehicle Details

| | |
|---|---|
| Chassis Number | 5N1DL0MM5K******* |
| Specification | GCC Specification |
| Make | Infiniti |
| Model | QX60 |
| Model Year | 2019 |
| Color | White |
| Mileage | 133078 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 6 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | **جسم المركبة** |
| 01.A Fenders | FRONT LEFT SIDE REFITTED | مدكار |
| 01.B Paint | BODY REPAINTED PORTION REPAIRED,EXCEPT ROOF,MINOR DENT SCRATCHES,PORTION RUSTY | الصبغ |
| 01.C Rusty | UNDER BODY PARTS GETTING RUSTY | صدأ |
| 01.D Bumper | MISALIGN PORTION MODIFIED HOLES,GRILL PORTION CRACK,REAR STRIP FIX BY SCREW | دعامية |
| 01.E Bonnet | STAY SHOCK NOT WORKING | غطاء المحرك |
| 01.F Trunk | AUTO NOT WORKING,REFITTED MISALIGN,REAR SWITCH DAMAGED | صندوق |
| 01.G Sign of back accident | BACK PANEL REPAIRED ,BUMPER FRAME DAMAGED | وجود مؤشر لحادث في الخلف |
| **02 Chassis Condition** | | **الشاصي** |
| 02.A Chassis | REAR LEFT SIDE CHASSIS BADLY HEATED BEND ,CRACK | الشاسيه |
| **03 Engine Condition** | | **المحرك** |
| 03.A Engine Visual Condition | MINOR OIL LEAK ,PARTS GETTING RUSTY ,COMPONENTS REFITTED | الحالة النظريه للمحرك |
| **04 Transmission Condition** | | **الجير** |
| 04.A Gear Box Visual Condition | MINOR OIL LEAK ,PARTS GETTING RUSTY | الحالة النظريه للجير |
| 04.B Propeller Shaft | MISSING | ناقل الحركة |
| 04.C Road Test | NOT CHECK | فحص علي الطريق |

| Condition | Remarks | الحالة |
|---|---|---|
| 04.D Four Wheel Drive | DISCONNECTED | الدفع الرباعي |
| **05 Tires and Rims Condition** | | الاطارات |
| 05.A Front Tyre | BOTH SIDE 2023 CRACKED WORN OUT | الاطار الامامي |
| 05.B Rear Tyre | BOTH SIDE 2023 CRACK | الاطار الخلفي |
| 05.C Rims Condition | DENTS SCRATCHES | حالة الجنوط |
| **06 Lights** | | الاضاءة |
| 06.A Tail Light | LEFT SIDE PORTION DAMAGED | الضوء الخلفي |
| 06.B Indicator & Hazard light | BOTH SIDE MIRROR INDICATOR LIGHT COVER DAMAGED | الاشارات |
| **07 Interior Condition** | | الحاله الداخليه |
| 07.A Other | INTERIOR PARTS GETTING RUSTY ,CENTER CONSOLE BOX COVER PORTION CRACKED | اخري |
| 07.B Mirror | LEFT SIDE COVER PORTION DAMAGED,BOTH SIDE INDICATOR LENS BROKEN | المرايا |
| 07.C AC Condition | LOW COOLING NOT WORKING PROPERLY | المكيف |
| 07.D Dash Board | LEATHER REPLACED | لوحة القياده |
| 07.E Door Panel | PORTION WORN OUT | لوحة بطانة الباب |
| 07.F Gear Shifting Lever | KNOB WORN OUT,SHIFT LOCK COVER MISSING | ذراع نقل السرعات |
| 07.G Engine Start Button | WORN OUT | زر تشغيل المحرك |
| **08 Engine Cooling System** | | نظام تبريد المحرك |
| 08.A Radiator Hose | COOLANT LEAK FROM ENGINE SIDE | خرطوم المبرد |
| **09 Battery Condition** | | حالة البطارية |
| 09.A Battery bracket | MISSING | حامل البطارية |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**