

Queue Number

2873175

Transaction Date

16 Oct 2026, 12:27:26

Site Name

840 - Emirates Auctions

Transaction Number

57506739 (CC10008) (CC10019)



Vehicle Details

Chassis Number

LSJA24W96L*****

Specification

GCC Specification

Make

MG

Model

HS

Model Year

2020

Color

Black

Mileage

77552 Miles

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

FRONT RIGHT SIDE REPAINTED REPAIRED , REFITTED

مدكار

01.B Paint

BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES

الصبغ

01.C Doors

REAR RIGHT SIDE REPAINTED PORTION REPAIRED,PORTION DENT

أبواب

01.D Rusty

UNDER BODY PARTS ,POWER TRAIN GETTING RUSTY

صدأ

01.E Bumper

MISALIGN , SKIRT PORTION LOOSE , HOOK COVER MISSING REAR LEFT SIDE REFLECTOR
PORTION DAMAGED

دعامية

01.F Bonnet

REPAINTED PORTION REPAIRED ,CRACK REFITTED & SHOCK NOT WORKING

غطاء المحرك

01.G Door Handle &Lock

REAR RIGHT SIDE OUTER HANDLE MISSING

مقابض الأبواب والأقفال

01.H Sign of front accident

وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis Extension

REAR RIGHT CHASSIS EXTENSION END RUSTY

تمديدات الشاسي

02.B Chassis

CHASSIS COVERED CHECKED VISIBLE AREA / OK

الشاسيه

03 Engine Condition

المحرك

03.A Other

TOP ENGINE COVER MISSING

اخرى

03.B Engine Visual Condition

OIL LEAK,REFITTED ,OIL MIX WITH COOLANT ,PARTS GETTING RUSTY,SHAKIG ,ABNORMAL
NOISY

الحالة النظرية للمحرك

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DRIVER SEAT FOLDING SWITCH NOT WORKING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED ,PARTS GETTING RUSTY ,DELAY SHIFTING ,JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2019 EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES,FRONT RIGHT SIDE HUB COVER MISSING	حالة الجنوط
07 Interior Condition		الحالة الداخلية
07.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
07.B AC Condition	OK	المكيف
07.C Dash Board	LEATHER PORTION LOOSE	لوحة القيادة
07.D Sunroof	CURTAIN DAMAGED	فتحت سقف
08 Engine Cooling System		نظام تبريد المحرك
08.A Coolant tank	OIL MIX WITH COOLANT	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae