

Queue Number

2870359

Transaction Date

15 Oct 2026, 16:43:35

Site Name

840 - Emirates Auctions

Transaction Number

70873744 (CC10013) (CC10011)



Vehicle Details

Chassis Number

1FAHP2F81F*****

Specification

Imported

Make

Ford

Model

Taurus

Model Year

2015

Color

Maroon

Mileage

76106 Miles

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders

FRONT LEFT SIDE REFITTED

مدكار

01.B Paint

BODY REPAINTED PORTION REPAIRED,EXCEPT ROOF,MINOR DENT SCRATCHES

الصبغ

01.C Rusty

UNDER FLOOR SUSPENSION PARTS GETTING RUSTY

صدأ

01.D Floor

UNDER FLOOR PORTION DENTS

الارضية

01.E Bumper

MISALIGN,SCRATCHES

دعامية

01.F Windshield

FRONT SPOT CRACK,COWL PANEL COVER PORTION DAMAGED MELTED

زجاج

01.G Roof

LEFT SIDE ROOF RAIL STRIP MISSING

السقف

01.H Trunk

REFITTED,REAR SWITCH NOT WORKING

صندوق

02 Chassis Condition

الشاسي

02.A Chassis

FRONT LEFT SIDE CHASSIS END BRACKET BEND

الشاسيه

03 Engine Condition

المحرك

03.A Mount

MOUNT RUBBER DRY CRACK

كرسي

03.B Engine Visual Condition

OIL LEAK DRIPPING , PARTS GETTING RUSTY

الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition

COVER PORTION DAMAGED WORN OUT

حالة المقاعد

05 Exhaust System

نظام العادم

Condition	Remarks	الحالة
05.A Other	DENT	اخرى
06 Transmission Condition		الاجير
06.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظره للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2026 WORN OUT	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
07.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LEFT SIDE NOT WORKING PROPERLY	الاضاءة الرئيسية
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER PORTION CRACKED LOCK HANDLE PART MISSING,INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED,CUP HOLDER COVER LOOSE PORTION DAMAGED	اخرى
10.B AC Condition	NO COOLING,GRILL PORTION DAMAGED	المكيف
10.C Power Window Switch And Glass	MAIN PANEL SWITCH DAMAGED	مفتاح النافذه و الزجاج
10.D Audio	SWITCH WORN OUT	صوتيات
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
10.G Engine Start Button	SMART KEY MISSING	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

