

Queue Number 2761500

Transaction Date 17 Sep 2026, 16:19:21

Site Name
840 - Emirates AuctionsTransaction Number
96002610 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WDDZH4CB6J*****
Specification	GCC Specification
Make	Mercedes
Model	E200
Model Year	2018
Color	Black
Mileage	85871 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR,CHASSIS ,ENGINE,GEAR BOX COVERED,NEED TO REMOVE BOTH SIDE FENDER INNER & UNDER ENGINE COVER FOR PROPER INSPECTION	الارضية
01.E Bumper	MISALIGN , PORTION CRACK	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED,REFITTED , LOGO DAMAGED	غطاء المحرك
01.G Trunk	REPAINTED PORTION REPAIRED , SWITCH LOOSE NOT WORKING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Belt	REAR LEFT SIDE NOT WORKING	حزام الأمان
----------------	----------------------------	-------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	PARTS REFITTED OIL WET GETTING RUSTY MINOR JERKING	الحالة النظرية للجير
--------------------------------	--	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Interior Condition		الحالة الداخليه
07.A Other	INTERIOR REFITTED	اخرى
07.B Mirror	VIEW MIRROR BACK COVER LOOSE , RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY , LEFT SIDE NOT WORKING	المرايا
07.C AC Condition	OK , CENTER GRILL PORTION DAMAGED	المكيف
07.D Dash Board	LEATHER REPLACED , RIGHT SIDE GRILL DAMAGED	لوحة القيادة
07.E Sun Visor	BOTH SIDE MIRROR COVER MISSING	حاجب الشمس

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae