

Queue Number 2915889

Transaction Date 27 Oct 2026, 15:59:47

Site Name
840 - Emirates AuctionsTransaction Number
79640337 (CC10009) (CC10025)

Vehicle Details

Chassis Number MHFYX59G7F*****
 Specification GCC Specification
 Make Toyota
 Model Fortuner
 Model Year 2015
 Color White
 Mileage 274059 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED , PORTION GETTING RUSTY , PAINT PORTION DAMAGED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS FULLY MUDDY PRTION DENT	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Trunk	REPAINTED PORTION REPAIRED REFITTED	صندوق
01.H Sign of back accident		وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS GETTING RUSTY,MINOR DENT OK	الشاسيه
--------------	-------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS REFITTED GETTINGRUSTY MINRO JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Tail Light	RIGHT SIDE PORTION DAMAGED	الضوء الخلفي
06.C Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	REAR RIGHT SIDE SUBFRAME BEND	ازرع مفصل كروي
08.B Arms	BUSHES CRAKCED	
08.C Ball Joint	BOOT CUT	
09 Steering Condition		المقود
09.A Steering Boot	BOOT CUT	ربلة المقود
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING REUSTY, SIGN OF FLOODED	اخرى
10.B AC Condition	OK	المكيف
10.C Audio	SWITCH DAMAGE NOT WORKING PROPERLY	صوتيات
10.D Roof Ceiling	FRONT RIGHT SIDE & REAR BOTH SIDE HANDLE MISSING	بطانة السقف
10.E Sun Visor	BOTH SIDE PORTION LOOSE	حاجب الشمس
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT , PORTION CRACK	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

