CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2949299
Transaction Date	06 Nov 2026, 16:19:13
Site Name	840 - Emirates Auctions
Transaction Number	99338871 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WBAKB81099*******
Specification	GCC Specification
Make	BMW
Model	750
Model Year	2009
Color	White
Mileage	110270 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE REPAINTED,PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.F Windshield	REAR CURTAIN NOT WORKING	زجاج
01.G Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE FRONT BOTH SIDE FENDER CHASSIS COVERS FOR RECHECK	اخري
03 Engine Condition		المحرك
03.A Engine Visual Condition	MINOR OIL LEAK REFITTED GETTING RUSTY, SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY, DELAY SHIFTTING	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	BOTH SIDE PORTION CRACKED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CUT	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحاله الداخليه
09.A Mirror	LEFT SIDE FOLDING NOT WORKING	المرايا
09.B AC Condition	NOT COOLING	المكيف
09.C Audio	SCREEN FADED	صوتيات
09.D Dash Board	LEATHER REPLACED ,RIGHT SIDE GRILL MISSING	لوحة القياده
09.E Engine Start Button	SWITCH FADED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae