CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2895487
Transaction Date	26 Oct 2026, 12:56:16
Site Name	840 - Emirates Auctions
Transaction Number	49266028 (CC10010) (CC10010)



Vehicle Details

Chassis Number	5TDBY64A1F*******
Specification	GCC Specification
Make	Toyota
Model	Sequoia
Model Year	2015
Color	White
Mileage	681504 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT ?& REAR BOTH SIDE REPAINTED PORTION REPAIRED .	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED. GRILL DAMAGED. LOOSE. MODIFIED.	دعامية
01.G Trunk	LOCK DAMAGED , LOOSE ,MISALIGN ,	صندوق
01.H Sign of front accident	BUMPER FRAME ,BULKHEAD FENDER FRAME REPAIRED/.	وجود مؤشر لحادث في المقدمة
01.I Sign of side accident	QUARTER PANEL WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في الجانب
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS FRAME COMPLETE RUSTY PORTION DENT , MUDDY .,	الشاسيه
02.B Chassis Number	VIN PUNCHING AREA GETTING RUSTY.	رقم القاعدة
03 Engine Condition		**المحرك**
03.A Mount	BUSHES CRACKED.	كرسي
03.B Smoke	BLACK	دخان
03.C Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
04.C Four Wheel Drive	NOT CHECKED.	الدفع الرباعي
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACKED DAMAGED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024/2023 CRACKED DAMAGED	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED.	الاضاءة الرئيسية
06.B Tail Light	PORTION CRACKED.	الضوء الخلفي
06.C Warning Light	EXTRA WARNING LIGHT/WARNING MESSAGE ON IN CLUSTER	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY ,WEAK .	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK ,HARD .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B Mirror	CENTER MIRROR LOOSE REMOVED	المرايا
10.C AC Condition	NOT COOLING.	المكيف
10.D Power Window Switch And Glass	FRONT RIGHT NOT WORKING.	مفتاح النافذه و الزجاج
10.E Roof Ceiling	LOOSE ,PORTION CUT .	بطانه السقف
10.F Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.H Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**