

Queue Number 2841555

Transaction Date 07 Oct 2026, 13:20:12

Site Name
840 - Emirates AuctionsTransaction Number
71608227 (CC10009) (CC10012)

Vehicle Details

Chassis Number	JTEGD52M08*****
Specification	GCC Specification
Make	Toyota
Model	Previa
Model Year	2010
Color	Silver
Mileage	660621 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED REPAIRED DENT SCRATCHES , PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS MUDDY PORTION DENT	الارضية
01.E Bumper	PORTION DAMAGED , GRILL DAMAGED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Fuel Tank	DENT	خزان الوقود
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FULLY MUDDY PORTION MINOR GETTING RUSTY,OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY MUDDY, SHAKING	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	WORN OUT , PORTION CUT	حالة المقاعد
---------------------	------------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK REFITTED GETTING RUSTY JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
06.C Rims Condition	RIGHT SIDE HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE MINOR CRACK	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Fog light	FADED , NOT WORKING , RIGHT SIDE COVER MISSING	كشف الضباب
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Hand Brake	NOT WORKING	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CUT	ازرع
09.B Other	SUSPENSION NOISY, REAR BOTH SIDE TRALLING BUSHES CUT	اخرى
09.C Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Steering Oil	MINOR OIL LEAK	زيت المقود
10.B Other	GETTING HARD	اخرى
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS RUSTY, SIGN OF FLOODED	اخرى
11.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING , LEFT SIDE LOOSE	المرايا
11.C AC Condition	OK , GRILL DAMAGED	المكيف
11.D Power Window Switch And Glass	FRONT RIGHT SIDE , REAR BOTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.E Dash Board	PORTION DAMAGED	لوحة القيادة
11.F Roof Ceiling	HAND GRAB COVER MISSING	بطانه السقف
11.G Sun Visor	LEFT SIDE MISSING	حاجب الشمس
11.H Odometer reading	DISPLAY FADED	قراءة عداد المسافات
11.I Door Panel	WORN OUT	لوحة بطانة الباب
11.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم



Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae