

Queue Number 2840686

Transaction Date 06 Oct 2026, 13:43:49

Site Name
840 - Emirates AuctionsTransaction Number
21412735 (CC10010) (CC10010)

Vehicle Details

Chassis Number	JTHBN36F15*****
Specification	Imported
Make	Lexus
Model	LS 430
Model Year	2005
Color	Blue
Mileage	283849 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA ,	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Fuel Tank	DENT	خزان الوقود
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL ,COMPARTMENT FLOOR REPAIRED,DENT .	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS END,REAR EXTENSION END REPAIRED DENT CHASSIS OILY MUDDY.PORION COVERED.	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED .	كرسي
03.B Smoke	WHITE	دخان
03.C Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	COVER DAMAGED .,	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Modification	CUT .REWELDED MODIFIED .	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظرية للجير
06.B Propeller Shaft	FLANGE BUSHES CRACKED.	ناقل الحركة
06.C Road Test	NOT CHECKED .	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025.	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2023 WORN OUT CRACKED.	الاطار الخلفي
07.C Rims Condition	MINOR DETNS SCRATCHES .	حالة الجنوط
08 Lights		الاضاءة
08.A Head Light	LENS FADED.	الاضاءة الرئيسية
08.B Warning Light	EXTRA WARNING LIGHT & MESSAGE ON IN CLUSTER.	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK , HARD STEERING .	جهاز المقود
10.C Axle	GREASE LEAKING BOOT CUT .	اكسلات
11 Interior Condition		الحالة الداخليه
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخرى
11.B Mirror	RIGHT SIDE FOLDING,ADJUSTMENT NOT WORKING FADED.	المرآيا
11.C AC Condition	NOT COOLING.	المكيف
11.D Floor Matting	CENTER CONSOLE BOX COVER DAMAGED ,LOCK LOOSE.	فرش الأرضيه
11.E Audio	NOT WORKING SCREEN FADED.	صوتيات
11.F Dash Board	PORTION LOOSE BULGED.	لوحة القيادة
11.G Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT HARD .	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات



Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae