

Queue Number 2740765

Transaction Date 11 Sep 2026, 15:13:38

Site Name
840 - Emirates AuctionsTransaction Number
44452369 (CC10021) (CC10011)

Vehicle Details

Chassis Number	SCBCR63W75*****
Specification	Imported
Make	Bentley
Model	Continental
Model Year	2005
Color	Black
Mileage	115604 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR RIGHT SIDE PORTION REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER BODY FLOOR CHASSIS , ENGINE , GEAR COVERED CHECK VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN SCRATCHES,GRILL PORTION MISSING	دعامية
01.F Trunk	NOT OPEN	صندوق
01.G Door Handle &Lock	BOTH SIDE DOOR OUTER HANDLE CHROME STRIP MISSING	مقابض الأبواب والأقفال

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	CHASSIS COVERED,NEED TO REMOVE BOTH SIDE FENDER & UNDER ENGINE COVER FOR PROPER INSPECTION	اخرى
02.C Chassis Number	CHASSIS NUMBER LAMINATED	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION WORN OUT,RIGHT SIDE ADJUSTMENT SWITCH PART MISSING	حالة المقاعد
---------------------	--	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED,PARTS GETTING RUSTY,JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	SWITCH PORTION WORN OUT,LEFT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX COVER WORN OUT,BOTH SLIDING COVER DAMAGED	اخرى
09.B Mirror	CENTER VIEW MIRROR BACK COVER LOOSE,RIGHT SIDE AUTO FOLDING NOT WORKING	المرآيا
09.C AC Condition	LOW COOLING,GRILL PORTION LOOSE	المكيف
09.D Power Window Switch And Glass	LEFT SIDE BOTH NOT WORKING,LOCK SWITCH STUCK	مفتاح النافذه و الزجاج
09.E Audio	SCREEN GETTING FADED	صوتيات
09.F Dash Board	PORTION WORN OUT,GLOVE BOX,LEFT SIDE LOWER PORTION MINOR LOOSE	لوحة القيادة
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT,DUST COVER DAMAGED	ذراع نقل السرعات
09.I Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

