

TEST CERTIFICATE

Site Number 840-Emirates Auctions Transaction Date 08 Jan 2023, 13:44:57

Transaction Number **27531783 (CC10009)** Queue Number **653678**



Chassis Number 1C4AJWAG4CL285580

Engine Number

Vehicle Class Car

Manufacturer Jeep

Model Wrangler

Model Year 2012
Color Black

Mileage 182142 Miles

Fuel Type Petrol

No. Of Cylinders 6

Specification Imported

DEFECT REMARKS

O1 Body		جسم المركبة
01.A Paint	BODY PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.B Doors	REPAINTED & REFITTED	أبواب
01.C Bumper	MODIFIED	دعامية
01.D Fenders	PORTION REPAIRED , REPAINTED & FRONT REFITTED (MODIFIED)	مدكار
01.E Pillars	LEFT SIDE DOOR PILLAR,ROCKER PANEL, FLOOR REPAIRED	القوائم
01.F Bonnet	REPAINTED	غطاء المحرك
01.G Trunk	PORTION REPAIRED & REPAINTED	صندوق
02 Interior Condition		الحاله الداخليه
02.A Mirror	CENTER MIRROR FADED	المرايا
02.B AC Condition	ОК	المكيف
03 Tires and Rims Condition		الاطارات
03.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
03.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة

DEFECT	REMARKS	
04 Transmission Condition		الجير
04.A Visual Gear Box Condition	SIGN OF MINOR OIL LEAK REFITTED	حالة الجير النظرى
04.B Road Test	NOT CHECK	فحص علي الطريق
O5 Lights		الاضاءة
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
05.B Head Light	LENS FADED & BOTH SIDE LOOSE	الاضاءة الرئيسية
06 Engine Condition		المحرك
06.A Visual Engine Condition	OIL LEAK, REFITTED	حالة المحرك النظرى
06.B Mount	MOUNT CRACK	كرسي
07 Chassis Condition		الشاصي
07.A Chassis	LEFT SIDE CHASSIS BEND & BODY MOUNT REPAIRED,FRONT CROSS MEMBER REPAIRED	الشاسيه
07.B Chassis Number	CHASSIS NUMBER STICKER MISSING	رقم القاعدة
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR BOTH SIDE BEND/ LEAK	ممتص الصدمات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير سارى.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate











Transfer Certificate: 66724969 1C4AJWAG4CL285580 Chassis No: Vehicle Make: Vehicle Model: **WRANGLER** Vehicle Class: Light Vehicle **Body Type: JEEP** Fuel: Benzene Color: Black **Drive Direction:** Dimensions: (H x W x L) **Current Odometer:** 293130 Kms Origin: United States Model Year: 2012 Engine Size: 3600 CC Gear Type: Automatic Engine No: NIL Horse 285 Power: Axles No: 2 Cylinders: 6 No Of No Of Seats: 5 Doors: G. V. W. : 2268 Kas. **Empty** 1759 Kas. Weight:

Certificate Number :		5-TAS-2023-18584477		
Inspection Date :		18-01-2023		
Certificate Print Date :		18-01-2023		
Services :		Registration Test		
Vehicle Testing Partner:		Tasjeel		
Vehicle Testing Center:		Tasjeel Al Aweer		
Total Time Taken:		16 min 7 sec		
Appointment Ref Number:				
Start	16:31	End Time: 16:47		
Time :		Token No.: 223		
Lane:	02	Prints No: 1		
Attempt	: 1			

Parameter Readings

Service brake imbalance on front axle

23 %

Service brake imbalance on rear axle
15 %

Parking brake imbalance between LHS and RHS $6\,\%$

Vehicle on Petrol CO Reading 0.41 %

Vehicle on Petrol HC Reading 39 PPM VOL

Inspection Findings

Defects	Issue	Severity
Shock Absorber replace rear both side shocks	Defective	Major
Gear/Differential	Oil leaking continuously	Major
Engine	Worn out rubber mountings	Major
Bulkhead/Cross member repair front crss member crack	Others (Major)	Major
Engine	Oil leaking continuously	Major

Inspection Remarks:

MIDDLE LEFT SIDE CHASSIS OUTER MINOR BEND , LEFT SIDE RUNNING BOARD REPAIRED , LEFT SIDE A & B PILLAR REPAIRED(OLD



Payment Details

Inspection Performed by 35063

Parking Slot No

Payment Method
Cash

Service Name Registration Test Transaction Number

Attempt 1

Service Fees

AED 170 Collected on 18/01/2023

Received by

Shawkat Mohamed Samir

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أُصدرَت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
30. يوم من تاريخ الفحص

