





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 23440195	Plate Category	: PRIVATE
Transaction Date	: 07 JAN 2021 13:18:31	Plate Number	: 130442 EA
Queue Number	: 277504	Import Doc. Ref.	:
Chassis Number	: 2T2ZZMCA4KC130442	Manufacturer/Model	: LEXUS/RX 350
Engine Number	:	Model Year	: 2019
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Failed	فحص ميزانية الاطارات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.03 - Steering Wheel, Change, Repair		مقبض عجلة القيادة
02.11 - Shock Absorbers		مخمد الصدمات
02.13 - Stub Axle Assemblies, Boots		المحور
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.03 - Doors		الابواب
05.05 - Bumpers		الدعامية
05.08 - Chassis (Frame)		الشاصية
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
06 General Items		الاشياء العامة
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 23440195	Plate Category	: PRIVATE
Transaction Date	: 07 JAN 2021 13:18:31	Plate Number	: 130442 EA
Queue Number	: 277504	Import Doc. Ref.	:
Chassis Number	: 2T2ZZMCA4KC130442	Manufacturer/Model	: LEXUS/RX 350
Engine Number	:	Model Year	: 2019
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident	BULKHEAD /RADIATOR SUPPORT REPAIRED	أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.23 - Air Bag Damaged	BOTH SIDE CURTAIN AIR BAG DEPLOYED & CUT	المخدة الهوائية لا تعمل
09.25 - Body Repainted		أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية</p>		

# Test Certificate



✓ PASS

Vehicle  
Registration



Possession Certificate : 64697606

Chassis No : 2T2ZZMCA4KC130442

Vehicle Make : LEXUS

Vehicle Model : RX 350

Vehicle Class : Light Vehicle

Body Type : STATION

Fuel : Benzene

Color : White

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 5817 Kms.

Origin : Canada

Model Year : 2019

Gear Type : --

Engine Size : 3500 CC

Engine No : NIL

Horse Power : 270

Axles No : 2

Cylinders : 6

No Of Doors : 5

No Of Seats : 5

G. V. W. :

2722 Kgs.

Empty Weight : 2020 Kgs.

Certificate Number : 5-MUT-2021-13315356

Inspection Date : 05-01-2021

Certificate Print Date : 05-01-2021

Services : Registration Test

Vehicle Testing Partner : Al Mutakamela Vehicle Testing LLC

Vehicle Testing Center : Al Mutakamela Vehicle Testing Al Qouz

Total Time Taken :  
13 min 7 sec

Appointment Ref Number : --

Start Time : 13:59

End Time : 14:12

Lane : 02

Token No. : 443

Attempt : 1

Prints No : 1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)



33 KM

Distance per  
year



4 L

Fuel consumed  
per year



7 AED

Fuel cost per  
year



0.1 ton

Carbon footprint  
per year

## Parameter Readings

Service brake imbalance on  
front axle

7 %

Service brake imbalance on  
rear axle

1 %

Parking brake imbalance  
between LHS and RHS

7 %

Vehicle on Petrol CO  
Reading

0.009 %

Vehicle on Petrol HC  
Reading

0 PPM VOL

## Inspection Remarks:

FRONT BOTH SIDE CHASSIS, BULKHEAD CROSS MEMBER BUMPER FRAME REPAIRED/DOOR PILLARS REPAIRED HAVING CCM REPORT OK, WORK ORDER NUMBER 2020008292 ATTACH ON PREVIOUS TEST. OLD

## Payment Details

Inspection Performed by

61989

Payment Method

Cash

Transaction Number

13315356

Service Fees

AED 170 Collected on 05/01/2021

Parking Slot No

--

Service Name

Registration Test

Attempt

1

Received by

Mohammed Nahed Mohamed  
Ahmed

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

