



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 27 May 2023, 11:21:01 |
| Transaction Number | 66391275 (CC10008) | Queue Number | 727857 |



| | |
|------------------|--------------------------|
| Chassis Number | 6G1ML54B98L957640 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Chevrolet |
| Model | Caprice LTZ |
| Model Year | 2008 |
| Color | Silver |
| Mileage | 368592 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 6 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|--------------------------------------------------------------|---------------------------|
| 01 Lights | | الاضاءة |
| 01.A Head Light | LENS FADED,RIGHT SIDE LOW BEAM NOT WORKING | الاضاءة الرئيسية |
| 01.B Warning Light | WARNING LIGHT ON DISPLAY | ضوء تحذير |
| 01.C Brake Light | RIGHT SIDE NOT WORKING | نور الفرامل |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Front Tyre | BOTH SIDE 2020,CRACKED | الاطار الامامي |
| 02.B Rear Tyre | BOTH SIDE 2020,CRACKED | الاطار الخلفي |
| 03 Body | | جسم المركبة |
| 03.A Paint | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES | الصبغ |
| 03.B Doors | REAR RIGHT SIDE REPAINTED,PORTION REPAIRED | أبواب |
| 03.C Bonnet | PORTION REPAIRED,REPAINTED,SHOCK WEAK | غطاء المحرك |
| 03.D Fenders | PORTION REPAINTED,PORTION REPAIRED | مدكار |
| 03.E Sign of side accident | | وجود مؤشر لحادث في الجانب |
| 04 Seats Condition | | المقاعد |
| 04.A Seat Condition | SIDE COVER LOOSE,PORTION DAMAGED | حالة المقاعد |

| DEFECT | REMARKS | |
|----------------------------------|----------------------------------------------------------------------|------------------------|
| 05 Interior Condition | | الحاله الداخليه |
| 05.A Door Panel | PORTION DAMAGED | لوحة بطانة الباب |
| 05.B Roof Ceiling | PORTION LOOSE | بطانه السقف |
| 05.C AC Condition | NOT COOLING | المكيف |
| 05.D Other | GEAR LEVER KNOB WORN OUT | اخرى |
| 05.E Power Window Switch | REAR LEFT SIDE NOT WORKING & MAIN SWITCH PANEL COVER PORTION DAMAGED | مفتاح النافذه |
| 06 Transmission Condition | | الجير |
| 06.A Road Test | NOT CHECK | فحص علي الطريق |
| 06.B Visual Gear Box Condition | JERKING | حالة الجير النظرى |
| 07 Suspension System | | ممتص الصدمات |
| 07.A Arms | LOWER ARM BUSH CRACKED | ازرع |
| 07.B Ball Joint | BOOT CUT | مفصل كروي |
| 08 Engine Condition | | المحرك |
| 08.A Visual Engine Condition | MINOR OIL LEAK | حالة المحرك النظرى |
| 08.B Smoke | BLACK SMOKE | دخان |
| 09 Chassis Condition | | الشاسي |
| 09.A Chassis | CHECKED VISIBLE AREA OK | الشاسيه |
| 10 Steering Condition | | المقود |
| 10.A Tie Rod End | BOOT CUT | مؤخرة الرودادت |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.