



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>28 Jul 2022, 13:16:25</b>
Transaction Number	<b>14205497 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1G1165S32FU120724</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Impala</b>
Model Year	<b>2015</b>
Color	<b>Grey</b>
Mileage	<b>202448 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Doors	FRONT LEFT SIDE & REAR BOTH SIDE PORTION REPAIRED , REPAINTED	أبواب
01.B Fenders	REAR BOTH SIDE PORTION REPAIRED, REPAINTED	مدكار
01.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.D Floor	UNDER FLOOR PORTION DAMAGED & DENT. CHASSIS AREA COVERED CHECKED VISIBLE AREA	الارضية
01.E Sign of side accident		وجود مؤشر لحادث في الجانب
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Mount	MOUNT BUSH CRACKED	كرسي
02.B Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
03.B Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
03.C Road Test	NOT CHECK	فحص علي الطريق
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>

DEFECT	REMARKS	
04.A Ball Joint	BOOT CRACKED	مفصل كروي
04.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
<b>05 Interior Condition</b>		<b>الحاله الداخليه</b>
05.A AC Condition	OK	المكيف
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Rear Tyre	LEFT SIDE 2017 CRACKED , EXPIRED & RIGHT SIDE 2021	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
07.B Other	FOR RECHECK PROPERLY REMOVE FENDER COVERS	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Custom Certificate :	12962496
Chassis No :	1G1165S32FU120724
Vehicle Make :	CHEVROLET
Vehicle Model :	IMPALA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	202437 Kms.
Origin : United States	Model Year : 2015
Gear Type : Automatic	Engine Size : 2000 CC
Engine No : nil	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2000 Kgs.	Empty 1550 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17216476		
Inspection Date :	17-07-2022		
Certificate Print Date :	17-07-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Barsha		
Total Time Taken :	11 min 47 sec		
Appointment Ref Number :	--		
Start Time :	17:00	End Time :	17:11
Lane :	04	Token No. :	541
Attempt :	1	Prints No. :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

84 KM	6 L	19 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 6 %	Service brake imbalance on rear axle 3 %	Parking brake imbalance between LHS and RHS 4 %	Vehicle on Petrol CO Reading 0.02 %
Vehicle on Petrol HC Reading 8 PPM VOL			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	2000	3500	

Inspection Remarks: rear right side q panel . rocker panel repaired . flooring minor dent

## Payment Details

Inspection Performed by 33722	Payment Method Credit Card	Transaction Number 17216476	Service Fees AED 170 Collected on 17/07/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Mohammed Abdul Kaleem

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.