



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 16 Jan 2023, 15:04:34 |
| Transaction Number | 62300744 (CC10009) | Queue Number | 656635 |



| | |
|------------------|--------------------------|
| Chassis Number | SCBCE63W27C041971 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Bentley |
| Model | GT Coupe |
| Model Year | 2008 |
| Color | Black |
| Mileage | 70223 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 12 |
| Specification | Imported |

| DEFECT | REMARKS | |
|------------------------------|---|----------------------------|
| 01 Engine Condition | | المحرك |
| 01.A Mount | MOUNT CRACK | كرسي |
| 01.B Visual Engine Condition | MINOR OIL LEAK /PARTS REFITTED | حالة المحرك النظري |
| 01.C Smoke | MINOR WHITE SMOKE | دخان |
| 02 Body | | جسم المركبة |
| 02.A Vehicle Year Model | AS PER CHASSIS NUMBER YEAR MODEL 2007 | سنة صنع المركبة |
| 02.B Paint | BODY PORTION REPAINTED,PORION REPAIRED, MINOR DENT,SCRATCHES | الصبغ |
| 02.C Fenders | FRONT BOTH SIDE , REAR RIGHT SIDE REPAIRED, REPAINTED & REFITTED | مدكار |
| 02.D Roof | ROOF RAIL PORTION REPAIRED,REPAINTED | السقف |
| 02.E Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 02.F Floor | UNDER FLOOR FENDER CHASSIS COVERED CHECKED VISIBLE AREA ONLY/FLOOR PORTION DENT | الارضية |
| 02.G Bumper | MISALIGN | دعامية |
| 02.H Doors | RIGHT SIDE REPAIRED REPAINTED & REFITTED | أبواب |
| 02.I Door Handle &Lock | RIGHT SIDE HANDLE LOOSE | مقابض الأبواب والأقفال |
| 02.J Bonnet | SHOCK WEAK & REPAINTED , REFITTED | غطاء المحرك |

| DEFECT | REMARKS | |
|------------------------------------|---|---------------------------|
| 02.K Sign of side accident | | وجود مؤشر لحادث في الجانب |
| 02.L Other | FRONT BUMPER FRAME BULK HEAD REFITTED | اخرى |
| 03 Interior Condition | | الحاله الداخليه |
| 03.A Roof Ceiling | LOOSE | بطانه السقف |
| 03.B Other | GEAR LEVER INNER COVER & REAR CONSOLE BOX COVER DAMAGED | اخرى |
| 03.C AC Condition | OK | المكيف |
| 03.D Power Window Switch | SWITCH LOOSE | مفتاح النافذه |
| 04 Suspension System | | ممتص الصدمات |
| 04.A Arms | LOWER ARM BUSHES CUT | ازرع |
| 04.B Ball Joint | BOOT CUT | مفصل كروي |
| 05 Chassis Condition | | الشاسي |
| 05.A Chassis | CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK | الشاسيه |
| 06 Tires and Rims Condition | | الاطارات |
| 06.A Rear Tyre | BOTH SIDE 2021 | الاطار الخلفي |
| 06.B Front Tyre | BOTH SIDE 2021 | الاطار الامامي |
| 07 Transmission Condition | | الجير |
| 07.A Visual Gear Box Condition | SIGN OF OIL WET | حالة الجير النظري |
| 07.B Road Test | NOT CHECK | فحص علي الطريق |
| 08 Lights | | الاضاءة |
| 08.A Warning Light | WARNING LIGHT ON IN DISPLAY | ضوء تحذير |
| 09 Brake Condition | | الفرامل |
| 09.A Hand Brake | NOT WORKING | فرامل اليد |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.