





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 21062435	Plate Category	: PRIVATE
Transaction Date	: 12 SEP 2020 10:41:03	Plate Number	: 0016739 EA
Queue Number	: 219470	Import Doc. Ref.	:
Chassis Number	: JTFPX22P690016739	Manufacturer/Model	: TOYOTA/HI ACE
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
01 Lights		الانوار
01.02 - Tail Lights		الانوار الخلفية
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.12 - Transmission Shaft, Flange Or Joint		عمود التعشيق
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
02.17 - Gear Box Mounting		كراسي ناقل الحركة
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.01 - Rusty		الصدأ
05.02 - Paint		الصبغ
05.05 - Bumpers		الدعامية
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
06 General Items		الاشياء العامة
06.01 - Wiper Blades		ماسحات الزجاج الامامي
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		حالة ناقل الحركة



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 21062435	Plate Category	: PRIVATE
Transaction Date	: 12 SEP 2020 10:41:03	Plate Number	: 0016739 EA
Queue Number	: 219470	Import Doc. Ref.	:
Chassis Number	: JTFPX22P690016739	Manufacturer/Model	: TOYOTA/HI ACE
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

06.16 - Engine Condition, Smoke	REFITTED/ ENGINE NOISE	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others	981244 KMS	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.15 - Sign Of Rear Accident	BACK PANEL REPAIRED/ DENT/ RUSTY	أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling	NOT COOLING	عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	ENGINE MALFUNCTION LIGHT ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صبغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		
شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية		

# Test Certificate



Vehicle  
Registration



RTA

X FAILED

Plate Details :	--
Chassis No :	JTFPX22P690016739
Vehicle Make :	TOYOTA
Vehicle Model :	HIACE
Vehicle Class :	Light Vehicle
Body Type :	VAN
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	981245 Kms.
Origin :	Japan
Model Year :	2009
Gear Type :	--
Engine Size :	2700 CC
Engine No :	8203209
Horse Power :	125
Axles No :	2
Cylinders :	4
No Of Doors :	5
No Of Seats :	3
G. V. W. :	Empty Weight : 1800 Kgs.
	2600 Kgs.

Certificate Number :	5-TAS-2020-12560310
Inspection Date :	16-09-2020
Certificate Print Date :	16-09-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Warsan
Total Time Taken :	17 min 50 sec
Appointment Ref Number :	--
Start Time :	11:07
End Time :	11:25
Lane :	01
Token No. :	129
Attempt :	1
	Prints No : 1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
1 %	37 %	73 %	0.1 %
Vehicle on Petrol HC Reading			
63 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Spare Tire <b>CHANGE SPARE TIRE CRACK AND WORN OUT</b>	Others (Major)	Major
Parking brake imbalance between LHS and RHS	More than 60% imbalance between LHS and RHS	Major
First Aid Box/Medical kit (commercial)	Missing	Major
Doors and Locks <b>FIX ALL DOOR PLASTIC CUR TON</b>	Missing	Major
Roof <b>REPAIR ROOF RUSTY</b>	Damaged/corroded	Major
Fire extinguisher (for commercial) <b>KEEP 2 KG</b>	Missing	Major
Tire <b>CHANGE FRONT RIGHT SIDE TIRE CRACK</b>	Cracked	Major
Warning triangle	Missing	Major
Service brake imbalance on rear axle	More than 30% imbalance between LHS and RHS	Major
Dip beams( Low Beams) headlight <b>REPAIR RIGHT SIDE HIGH&amp;LO-BEAM NOT WORKING</b>	Busted bulb	Major
Wiper arms, Blades, Washer <b>CHANGE WIPER BLADE</b>	Damaged or bend wiper arm(s) (Major)	Major
Transmission flange, joints, propeller shaft <b>CHANGE PROPELLER SHAFT CENTER BEARING WORN OUT</b>	Worn-out bearing/rubber mounting (Major)	Major
Vehicle Floor <b>REPAIR FRONT RIGHT SIDE FLOORING RUSTY HOLE</b>	Damaged/heavily corroded	Major
Dubai Municipality <b>BRING CALIBRATION CERTIFICATE(</b>	No document from authority	Major